

DAMAGE REPORT

Inbound carrier: JULIUS S
JULS129S 129S 23-Jul-2021 00:44

Container	Damage type	Damage location
PONU0419820	CUT	TARPAULIN
MAEU4685836	CUT	TARPAULIN
MAEU4695259	CUT	TARPAULIN
MRSU3625981	HOLE	TOPROOF
MAEU4677492	CUT	TARPAULIN
MAEU4670456	CUT	TARPAULIN
MAEU4673162	CUT	TARPAULIN
MAEU4706435	CUT	TARPAULIN
MAEU4661650	CUT	TARPAULIN
MAEU4671956	CUT	TARPAULIN
MRKU7542389	BENT	RIGHT
MRKU9208508	DENT	RIGHT
MAEU4683860	CUT	TARPAULIN
GATU8779874	DENT	RIGHT
GATU8779874	HOLE	TOPROOF
TCLU5238812	BENT	LEFT
MAEU4716536	CUT	TARPAULIN
BEAU5112628	DENT	LEFT
MRKU5865464	BENT	LEFT
MRKU8868446	DENT	RIGHT
MAEU4728218	CUT	TARPAULIN
MAEU4705104	CUT	TARPAULIN
MAEU4665151	CUT	TARPAULIN
MAEU4642726	CUT	TARPAULIN
MAEU4637782	CUT	TARPAULIN
MAEU4658595	CUT	TARPAULIN
MAEU4728840	CUT	TARPAULIN
MSKU1900194	DENT	RIGHT

Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
SUDU2861727	CUT	TARPAULIN
TTNU2490245	DENT	LEFT
MRSU4005497	BENT	RIGHT
SUDU8543390	DENT	CORNERPOST
PONU1467905	DENT	LEFT
SUDU6733658	DIRTY	FRONT
MSKU7212096	CUT	DOOR
MSKU7212096	CUT	BACK
MSKU7678079	DENT	CORNERPOST
MSKU7678079	DENT	CORNER
MSKU7678079	DENT	DOORSYSTEM
PONU8103910	BENT	LEFT
MAEU4679350	CUT	TARPAULIN
HASU1222652	TORN	DOORSYSTEM
HASU1222652	CUT	DOORSYSTEM
HASU1222652	CUT	BACK
HASU1222652	RIP	DOORSYSTEM
MAEU4653931	CUT	TARPAULIN
MRKU8120310	IMO LABEL	RIGHT
MAEU4683807	CUT	TARPAULIN
MAEU4656000	CUT	TARPAULIN
MRKU0485348	BENT	RIGHT
MRSU3677753	BENT	RIGHT
MRKU5996417	DENT	LEFT
PONU7794361	DENT	LEFT
SUDU2842516	CUT	TARPAULIN
MAEU4730658	CUT	TARPAULIN
TCKU7255663	DENT	LEFT
HASU1430701	DENT	FRONT
MSKU3194918	DENT	LEFT
TCLU6184407	TORN	DOORSYSTEM
MSKU1379403	DENT	CORNERPOST
MIEU2011224	DENT	LEFT