

DAMAGE REPORT

Inbound carrier: SAFMARINE
SNKR110S 110S 12-Mar-2021 02:42

| Container | Damage type | Damage location |
|-------------|-------------|-----------------|
| PONU8154733 | DENT | LEFT |
| PONU2053622 | DENT | RIGHT |
| PONU2053622 | BENT | RIGHT |
| MRKU4055833 | DENT | RIGHT |
| MRKU6618746 | BENT | RIGHT |
| MRKU6618746 | DENT | RIGHT |
| PONU0086817 | BENT | BOTTOM |
| MRKU8834955 | DENT | RIGHT |
| MRKU8834955 | BENT | LEFT |
| MRKU8834955 | DENT | LEFT |
| MSKU1408184 | DENT | LEFT |
| TCNU8229278 | HOLE | TOPROOF |
| TRIU0529039 | CUT | TARPAULIN |
| MRKU4313413 | DENT | LEFT |
| MSKU5128577 | DENT | LEFT |
| MRKU9268338 | CUT | LEFT |
| SUDU5274810 | CUT | LEFT |
| MSKU5756613 | BENT | RIGHT |
| MSKU5756613 | BENT | LEFT |
| SEKU4686510 | BENT | RIGHT |
| MRKU6271092 | BENT | FRONT |
| MSKU2378464 | DENT | RIGHT |
| MRKU9698658 | DENT | RIGHT |
| PONU4953140 | DENT | RIGHT |
| PONU4953140 | DENT | LEFT |
| MSKU7956605 | BENT | BOTTOM |
| MRKU7902839 | BENT | BOTTOM |
| MAEU4682328 | CUT | TARPAULIN |

Without any liability accepted
 Constanta South Container Terminal
 Planning Department

| Container | Damage type | Damage location |
|-------------|-------------|-----------------|
| CAIU4990346 | DENT | FRONT |
| HASU1022593 | DENT | LEFT |
| MAEU4710477 | CUT | TARPAULIN |
| MAEU4680670 | CUT | TARPAULIN |
| SUDU2838882 | CUT | TARPAULIN |
| PONU8151164 | DENT | RIGHT |
| MRSU4167414 | DENT | RIGHT |
| SUDU6875020 | DENT | RIGHT |
| MSKU8634429 | DENT | LEFT |
| CADU7019568 | DENT | LEFT |
| MSKU1442194 | DENT | LEFT |
| MNBU3525640 | DENT | CORNER |
| MNBU3269569 | DENT | TOPROOF |
| MNBU3269569 | TORN | TOPROOF |
| PONU2045870 | BENT | BOTTOM |
| MRKU3783984 | DENT | LEFT |
| MRSU4034068 | DENT | RIGHT |
| MIEU3005627 | DENT | RIGHT |
| PONU0137637 | DENT | LEFT |
| MRKU9752677 | BENT | LEFT |

Without any liability accepted
Constantia South Container Terminal
Planning Department