

DAMAGE REPORT

Inbound carrier: SAFMARINE
SNKR128S 128S 16-Jul-2021 04:40

| Container | Damage type | Damage location |
|-------------|-------------|-----------------|
| TRLU3912895 | BENT | LEFT |
| MSKU7693957 | BENT | BOTTOM |
| TEMU2100771 | BENT | BOTTOM |
| MSKU7137789 | DENT | CORNERPOST |
| MRKU3930107 | DENT | FRONT |
| MAEU3523281 | CUT | TARPAULIN |
| UESU4562581 | HOLE | BACK |
| MRKU8704308 | DENT | CORNER |
| PONU1896833 | BENT | LEFT |
| PONU1896833 | BENT | FRONT |
| MRKU8099341 | CUT | FRONT |
| MRKU5201594 | DENT | LEFT |
| HASU4216289 | DENT | LEFT |
| SUDU7421783 | TORN | DOORSYSTEM |
| MRKU5207756 | BENT | LEFT |
| MAEU4218620 | CUT | TARPAULIN |
| MSKU7361000 | BENT | BOTTOM |
| MSKU2624547 | DENT | LEFT |
| MAEU3503109 | CUT | TARPAULIN |
| SUDU8757324 | DENT | RIGHT |
| MAEU3518881 | CUT | TARPAULIN |
| MRSU3355994 | BENT | LEFT |
| MRSU3355994 | BENT | RIGHT |
| TLLU5254067 | DENT | RIGHT |
| MAEU3425808 | CUT | TARPAULIN |
| TCLU2307442 | DENT | LEFT |
| TGHU0771366 | BENT | BOTTOM |
| CAIU8255988 | HOLE | TOPROOF |

Without any liability accepted
Constanta South Container Terminal
Planning Department

SNKR128S

128S

16-Jul-2021 04:40

Container

Damage type

Damage location

HASU1021323

DENT

FRONT

Without any liability accepted
Constanta South Container Terminal
Planning Department