


**DAMAGE REPORT**

Inbound carrier: SAFMARINE NUBA  
NUBA103S 103S 21-Jan-2021 17:49

Container	Damage type	Damage location
MSKU1059246	DENT	RIGHT
TRHU4942920	DENT	LEFT
MRKU3308541	DENT	RIGHT
MRKU2695699	DENT	LEFT
MSKU0557183	DENT	RIGHT
SUDU5321785	DENT	LEFT
MRKU0139767	DENT	RIGHT
CAIU6135155	DENT	FRONT
MRKU5064613	BENT	RIGHT
MRKU5064613	DENT	LEFT
SUDU4972442	DENT	DOORSYSTEM
TRLU7635171	BENT	RIGHT
MRKU3605806	DENT	RIGHT
TCKU6855339	DENT	DOORSYSTEM
TRLU7512114	BENT	RIGHT
MRKU5312514	DENT	LEFT
MRKU4040767	CUT	LEFT
MRKU4040767	HOLE	LEFT
SUDU8619515	DENT	RIGHT
MRKU3905819	BENT	FRONT
MRSU3689040	BENT	LEFT
MRSU3689040	BENT	BOTTOM
TGHU8132145	DENT	RIGHT
CAAU5772310	DENT	RIGHT
CAAU5772310	DENT	LEFT
MAGU5124740	DENT	RIGHT
MSKU8312119	BENT	DOOR
MRKU2137104	DENT	LEFT

  
SAFMARINE NUBA  
OFF. NO.: HK-3610  
HONG KONG  
CALL SIGN: VRLA5  
GT: 25,904  
BHP: 29,200

REMARKS: DISCHARGED AS LOADED


  
Without any liability accepted  
Constanta South Container Terminal  
Planning Department

NUBA103S


103S

21-Jan-2021 17:49

Container	Damage type	Damage location
MRKU2137104	BENT	RIGHT
MRSU3339530	BENT	RIGHT
MRKU4363923	DENT	RIGHT
MRKU4363923	BENT	RIGHT
HASU4389094	DENT	FRONT
MRKU0483670	DENT	RIGHT
SUDU8535055	DENT	DOOR
MRKU2740822	DENT	LEFT
MNBU4216624	DENT	BOTTOM
MSKU3326634	DENT	FRONT
SUDU5845041	HOLE	TOPROOF
GATU1013594	DENT	LEFT
MRKU6918384	DENT	LEFT
SUDU8671581	DENT	FRONT
MRKU4793713	DENT	RIGHT
MRKU4793713	BENT	RIGHT
MRKU4793713	DENT	LEFT
MRKU4793713	BENT	LEFT
MSKU8945396	DENT	LEFT
HASU4396874	DENT	RIGHT
MWCU6769256	BENT	LEFT
MIEU0013613	DENT	RIGHT
MIEU0013613	BENT	BOTTOM
MSKU0357586	DENT	CORNERPOST
TCKU3505105	DENT	FRONT
SUDU2830109	CUT	TARPAULIN
MAEU3430609	CUT	TARPAULIN
MSKU0584996	DENT	CORNER
TCNU1478962	DENT	RIGHT
TCNU1478962	BENT	LEFT
MRKU6464126	BENT	RIGHT
MRKU6464126	DENT	RIGHT
MRKU6464126	BENT	LEFT
MRKU6464126	DENT	LEFT

  
 SAFMARINE NUBA  
 OFF. NO.: HK-3610  
 HONG KONG  
 CALL SIGN: VRLA5  
 GT: 25,904  
 BHP: 29,200

REMARKS: DISCHARGED AS LOADED


  
 Without any liability accepted  
 Constantia South Container Terminal  
 Planning Department

NUBA103S


103S

21-Jan-2021 17:49

Container	Damage type	Damage location
MRKU0907187	DENT	RIGHT
MRKU3577350	BENT	RIGHT
MRKU3577350	BENT	LEFT
FSCU8277794	DENT	LEFT
PONU7863800	BENT	RIGHT
PONU7863800	DENT	RIGHT
MSKU4404367	BENT	FRONT

  
SAFMARINE NUBA  
OFF. NO.: HK-3610  
HONG KONG  
CALL SIGN: VRLA5  
GT: 25,904  
BHP: 29,200

REMARKS: DISCHARGED AS LOADED

  
Page 3 of 3  
Constanta South C  
Planning D