

DAMAGE REPORT

Inbound carrier: SAFMARINE NUBA
NUBA127S 127S 08-Jul-2021 21:37

Container	Damage type	Damage location
MRKU4427870	DENT	LEFT
MSKU1931282	DENT	RIGHT
GCXU5723242	BENT	RIGHT
GCXU5723242	BENT	LEFT
MRKU0976824	DENT	FRONT
MSKU9242736	BENT	LEFT
SUDU7651528	BENT	RIGHT
MSKU3036194	DENT	CORNER
MRKU2104287	BENT	RIGHT
MRKU2104287	DENT	RIGHT
MRKU2104287	HOLE	RIGHT
MSKU4243386	IMO LABEL	FRONT
MSKU4243386	IMO LABEL	LEFT
MSKU4243386	IMO LABEL	DOOR
MSKU4243386	IMO LABEL	RIGHT
PONU0393921	DENT	DOORSYSTEM
TCKU6796792	BENT	LEFT
MSKU1077656	BENT	RIGHT
MSKU1077656	DENT	RIGHT
MSKU9423950	BENT	LEFT
MSKU9423950	DENT	FRONT
MRKU7926300	BENT	RIGHT
SUDU6727655	HOLE	RIGHT
MRKU0686701	HOLE	TOPROOF
MRKU0686701	DENT	TOPROOF
PONU0343793	DENT	CORNERPOST
PONU0343793	CUT	CORNER
PONU0343793	DENT	CORNER

Without any liability accepted
Constanta South Container Terminal
Planning Department

Boat

Page 1 of 2
SAFMARINE NUBA
OFF. NO.: HK-3610
HONG KONG
CALL SIGN: VRLA5
GT: 25,904
BHP: 29,200

REMARKS: DISCHARGED AS LOADED

NUBA127S

127S

08-Jul-2021 21:37

Container	Damage type	Damage location
MSKU2610610	DENT	LEFT
MSKU5114568	DENT	LEFT
PONU7646770	DENT	RIGHT
CAAU5402399	BENT	FRONT
MRKU2684591	DENT	RIGHT
MSKU9509740	DENT	LEFT
TCNU6290828	HOLE	TOPROOF
MRSU4723107	HOLE	TOPROOF
MRKU3941734	DENT	RIGHT
MRKU3941734	BENT	RIGHT
MRKU3941734	DENT	LEFT
MRKU3941734	BENT	LEFT
HASU4684206	DENT	RIGHT

Without any liability accepted
Constanta South Container Terminal
Planning Department

Boat

SAFMARINE NUBA
OFF. NO.: HK-3610
HONG KONG
CALL SIGN: VRLA5
GT: 25,904
BHP: 29,200

REMARKS: DISCHARGED AS LOADED