

DAMAGE REPORT

Inbound carrier: SAFMARINE NUBA

NUBA303S

303S

22-Jan-2023 00:14

Container	Damage type	Damage location
MRKU2114480	BENT	LEFT
MSKU8380406	BENT	RIGHT
TCNU5815470	BENT	RIGHT
TCNU5815470	DENT	LEFT
MRKU0429196	DENT	CORNERPOST
MRSU0288629	DENT	FRONT
MRKU7129061	DENT	RIGHT
MRKU7129061	BENT	RIGHT
MRSU0119146	BENT	RIGHT
MMAU1057303	DENT	CORNERPOST
FFAU2281620	BENT	RIGHT
FFAU2281620	BENT	LEFT
PONU7595544	DENT	LEFT
CAIU8317879	DENT	LEFT
TCKU1105774	BENT	LEFT
TCKU1105774	DENT	LEFT
MSKU7479312	BENT	RIGHT
MSKU7479312	DENT	RIGHT
MSKU3335600	DENT	LEFT
MSKU7145824	DENT	RIGHT
MSKU5825057	DENT	CORNER
HASU4131140	DENT	CORNERPOST
MRSU6230882	IMO LABEL	LEFT
MSKU5111759	DENT	CORNERPOST
MSKU5111759	TORN	CORNERPOST
MSKU5111759	DENT	CORNER
MSKU5111759	HOLE	FRONT
MSKU5111759	DENT	RIGHT

MSKU5111759
Without any liability accepted
Constanta South Container Terminal
Planning Department

SAFMARINE NUBA
OFF. NO.: HK-3610
HONG KONG
CALL SIGN: VRLA5
GT: 25,904
BHP: 29,200
DISCHARGE AS
LOA 1)

Container	Damage type	Damage location
HASU1335978	DENT	FRONT
MRKU7330667	HOLE	LEFT
MRKU7330667	BENT	LEFT
TLLU2493031	DENT	CORNERPOST
HASU1249226	DENT	RIGHT
MSKU5015776	DENT	LEFT
MRKU9251675	DENT	CORNERPOST
SUDU5144421	BENT	RIGHT
SUDU5144421	DENT	LEFT
TCKU2855006	CUT	FRONT
TCKU2855006	BENT	BOTTOM
TCKU2855006	DENT	FRONT
TGBU6631077	DENT	CORNERPOST
PONU8004245	DENT	LEFT
MRKU6899936	DENT	LEFT
MRSU0025854	DENT	RIGHT
MRKU5830529	DENT	CORNERPOST
MRSU3305381	HOLE	TOPROOF
CNIU2165272	DENT	LEFT
MRKU6836877	DENT	RIGHT
HASU1096894	DENT	RIGHT
HASU1096894	BENT	RIGHT
HASU1096894	DENT	LEFT
HASU1096894	BENT	LEFT
MSKU3398439	BENT	RIGHT
MSKU3398439	DENT	RIGHT
MSKU6580051	DENT	RIGHT
SUDU6940969	HOLE	TOPROOF
MRKU8097992	BENT	RIGHT
MSKU3611734	IMO LABEL	LEFT
MSKU3611734	IMO LABEL	FRONT
MSKU3611734	IMO LABEL	RIGHT
MSKU3611734	IMO LABEL	BACK
SUDU1823682	DENT	DOORSYSTEM

Without any liability accepted
Constanta South Container Terminal
Planning Department

SAFMARINE NUBA
OFF. NO.: HK-3610
HONG KONG
CALL SIGN: VRLA5
GT: 25,904
BHP: 20,200
Discipline
RS
WAT

Container	Damage type	Damage location
SUDU1823682	BENT	DOORSYSTEM
MRKU7692310	DENT	LEFT
TCLU8250745	DENT	RIGHT
MSKU6488921	BENT	RIGHT
MSKU6488921	DENT	RIGHT
MSKU6488921	DENT	CORNERPOST
MRSU4241698	DENT	LEFT
CAXU7348809	DENT	RIGHT
CAXU7348809	DENT	CORNERPOST
MSKU1369107	DENT	LEFT
CAAU5473216	BENT	RIGHT
SUDU1936539	BENT	RIGHT
MRKU3462768	BENT	RIGHT
HASU1206564	DENT	RIGHT
HASU1284166	CUT	FRONT
MSKU1226641	DENT	LEFT
MRKU8583989	DENT	RIGHT
MRKU8486607	DENT	LEFT
MSKU4208913	DENT	RIGHT
MRKU2241720	DENT	RIGHT
PONU0424046	DENT	RIGHT
MRKU8849636	BENT	RIGHT
MRKU8849636	DENT	RIGHT
MRKU7680259	BENT	LEFT
TEMU2374073	DENT	FRONT
MRKU9869508	BENT	RIGHT
MSKU7737551	BENT	RIGHT
MSKU7737551	BENT	LEFT
MRKU9874206	DENT	RIGHT
HASU1204812	BENT	LEFT
HASU1204812	DENT	LEFT
TCKU6849589	DENT	RIGHT
PONU7531350	DENT	RIGHT
MRKU4805856	DENT	CORNERPOST

Without any liability accepted
Constantia South Container Terminal
Planning Department

SAFMARINE NUBA
OFF. NO.: HK-3610
HONG KONG
CALL SIGN: VRLA5
DISC: 23,904
L.A.S: 20,200

LOA17

Container	Damage type	Damage location
HASU4617152	BENT	BOTTOM
MSKU5757796	IMO LABEL	FRONT
MSKU5757796	IMO LABEL	RIGHT
MSKU5757796	IMO LABEL	BOTTOM
MNBU3355081	DENT	RIGHT
SUDU1808800	DENT	LEFT
MRKU9065536	DENT	FRONT
TCLU4454967	DENT	RIGHT
MSKU3803280	DENT	RIGHT
MSKU3803280	DENT	CORNERPOST
MSKU5818171	DENT	RIGHT
MAEU3506807	CUT	TARPAULIN
MSKU7887150	DENT	RIGHT
TEMU2564303	DENT	RIGHT
MSKU6736062	DENT	CORNERPOST
MSKU8850114	BENT	RIGHT
MSKU8850114	DENT	CORNERPOST
SUDU6959162	DENT	LEFT
MSKU9497059	DENT	RIGHT
MSKU9497059	DENT	LEFT
SUDU6532930	DENT	LEFT
SUDU5939670	DENT	LEFT
MRKU5081272	BENT	RIGHT
MRSU5985755	DENT	RIGHT
MNBU0094282	DENT	LEFT
MRKU8250360	DENT	RIGHT
PONU2067523	DENT	FRONT
TCKU7631729	DENT	LEFT
SUDU7470704	DENT	RIGHT
MAEU3439761	CUT	TARPAULIN
MSKU3287991	DENT	RIGHT
MSKU3287991	DENT	LEFT
MSKU3287991	BENT	BOTTOM
MRKU2233237	DENT	LEFT

Without any liability accepted
Constantia South Container Terminal
Planning Department

SAFMARINE NUBA
OFF. NO.: HK-3610
HONG KONG
CALL SIGN: VRLA5
GT: 25,904
DRAUGHT: 12.00

AS

LOAD

Container	Damage type	Damage location
MRKU5691871	DENT	LEFT
MSKU3441957	DENT	RIGHT
MRKU0681459	DENT	CORNERPOST
PONU7592150	DENT	RIGHT
SEKU4599605	BENT	LEFT
MRKU3645558	DENT	LEFT
TGBU6314391	DENT	LEFT
MRKU5869480	BENT	FRONT
MRKU4560687	BENT	LEFT
BEAU5739161	DENT	RIGHT
MSKU9653594	DENT	LEFT
TCLU7099608	CUT	TARPAULIN
TCLU7099608	DENT	CORNERPOST
TCLU7099608	BENT	LEFT
PONU0382249	DENT	DOOR
MRKU7040349	IMO LABEL	RIGHT
MRKU7040349	IMO LABEL	LEFT
MRSU5331311	DENT	LEFT
TCLU7029257	CUT	TARPAULIN
TCLU7034865	DENT	RIGHT
TCLU7034865	CUT	TARPAULIN
TLLU4699910	DENT	RIGHT
TCKU1089668	BENT	RIGHT
CNIU2164846	BENT	LEFT
CAIU2484312	DENT	RIGHT
CAIU2484312	BENT	RIGHT
MAEU3503602	CUT	TARPAULIN
MAEU3503602	DENT	BOTTOM
MRKU6287967	HOLE	TOPROOF
MRKU6287967	DENT	LEFT
MRKU2536790	DENT	LEFT
MRKU2536790	DENT	RIGHT
MRKU2956600	DENT	LEFT
MRKU2956600	BENT	LEFT

Without any liability accepted
Constantia South Container Terminal
Planning Department

SAFMARINE NUBA
OFF. NO.: HK-3610
HONG KONG
CALL SIGN: VRLA5
GT: 25,904
Dismantled
2021

Container	Damage type	Damage location
MRKU0675610	DENT	RIGHT
UETU5850312	BENT	RIGHT
UETU5850312	DENT	RIGHT
MRKU3193988	DENT	RIGHT
CNIU2235467	BENT	RIGHT
PONU0449846	CUT	RIGHT
MSWU1011095	DENT	RIGHT
MSWU1011095	DENT	LEFT
SUDU5261238	DENT	RIGHT
MRKU7280890	DENT	RIGHT
MRKU7280890	BENT	BOTTOM
MRKU7280890	DENT	LEFT
TCNU1122396	DENT	RIGHT
TCKU1192510	DENT	CORNER
XINU1108979	DENT	CORNERPOST
PONU0652405	DENT	RIGHT
MSKU3925864	DENT	CORNERPOST
PONU0066277	DENT	LEFT
HASU1084065	DENT	RIGHT
MSKU0182955	DENT	LEFT
MSKU1238128	DENT	RIGHT
MAEU4648909	CUT	TARPAULIN
MRKU3366580	DENT	RIGHT
MRKU8557927	DENT	CORNERPOST
HASU1221825	DENT	RIGHT
MRKU6246037	DENT	RIGHT
SUDU6054997	DENT	RIGHT
MSKU2873581	DENT	LEFT
MSKU5978098	DENT	FRONT
MSKU7651798	BENT	BOTTOM
MSKU7651798	DENT	CORNERPOST
MRKU8180854	DENT	DOORSYSTEM
MRKU8180854	DENT	DOOR
MRKU8180854	TORN	DOORSYSTEM

Without any liability accepted
 Constantia South Container Terminal
 Planning Department

SAFMARINE NUBA
 OFF. NO.: HK-3610
 HONG KONG
 CALL SIGN: VRLA5
 GT: 25,904
 DISEASE 200
 (155 1021)

Container	Damage type	Damage location
SUDU5149510	DENT	LEFT
HASU1371553	DENT	CORNERPOST
HASU1371553	TORN	CORNERPOST
HASU1371553	HOLE	FRONT
HASU1371553	DENT	CORNER
HASU1371553	DENT	RIGHT
MSKU3313025	BENT	LEFT
MRKU9353620	DENT	RIGHT
MSKU1997593	DENT	LEFT
PONU0623691	DENT	RIGHT

Without any liability accepted
Constanta South Container Terminal
Planning Department

SAFMARINE NUBA
OFF NO.: HK-3610
HONG KONG
CALL SIGN: VRLA5
GT: 25,904
DWP: 23,200