

DAMAGE REPORT

Inbound carrier: MAERSK NAKURU
MNKR343S 343S 31-Oct-2023 12:41

Container	Damage type	Damage location
MAEU4068650	CUT	TARPAULIN
MRSU3544679	CUT	BOTTOM
MAEU4155409	CUT	TOPROOF
MAEU4655180	CUT	TARPAULIN
TCNU8215103	BENT	RIGHT
MRSU4259850	CUT	FRONT
MAEU4685100	CUT	TARPAULIN
MRSU3526628	DENT	LEFT
MAEU4192090	CUT	TOPROOF
TRHU7740100	BENT	RIGHT
MAEU4105938	CUT	TOPROOF
CAXU6946431	BENT	RIGHT
CAXU6946431	DENT	DOORSYSTEM
TLLU2471053	DENT	LEFT
TLLU2471053	BENT	BOTTOM
MRKU5543339	BENT	LEFT
MRKU5543339	DENT	RIGHT
CAIU4995008	HOLE	TOPROOF
MRKU4787937	DENT	RIGHT
MRKU4787937	BENT	LEFT
SUDU7303230	BENT	RIGHT
MSKU0825244	IMO LABEL	RIGHT
MSKU0825244	IMO LABEL	LEFT
MAEU4151070	CUT	TARPAULIN
MSKU1609851	DENT	LEFT
TLLU5977678	BENT	RIGHT
MAEU4082540	CUT	TARPAULIN
MRKU9529719	BENT	BOTTOM

FOR RECEIPT ONLY
WITHOUT ANY PREJUDICE
CONTAINER NOT SHOWN
TO DUTY OFFICER

MAERSK NAKURU
OFF HK-3605 Call Sign VRKZ8
POR: HONG KONG
GRT: 25,904 BHP: 29,200

Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
MRSU0050590	TORN	CORNERPOST
MRSU4627314	IMO LABEL	FRONT
MAEU4219226	CUT	TARPAULIN
MSKU5680631	DENT	CORNERPOST
MRSU3578262	DENT	LEFT
MSKU7086090	BENT	CORNERPOST
MAEU4122386	CUT	TARPAULIN
MSKU5159876	DENT	LEFT
MSKU3617922	DENT	LEFT
MSKU7272496	BENT	DOORSYSTEM
TCKU3581698	DENT	RIGHT
MRKU6566600	DENT	LEFT
MRKU6566600	BENT	RIGHT
MRKU9105665	BENT	LEFT
MRSU5735864	BENT	RIGHT
MRSU5735864	BENT	LEFT
MRKU4362608	DENT	RIGHT
MRKU8182440	BENT	LEFT
MRKU3293190	DENT	LEFT
MSKU9340795	DENT	LEFT
SUDU9800322	CUT	TOPROOF
MRKU5543010	DENT	LEFT
MSKU7751987	DENT	RIGHT
MRKU2138163	DENT	RIGHT
TGHU6754617	DENT	LEFT
MRKU5021817	DENT	LEFT
CRXU9263942	IMO LABEL	RIGHT
MSKU1842400	DENT	LEFT
MAEU4165794	CUT	TOPROOF
PONU0480944	DENT	CORNER
MRKU8178060	BENT	RIGHT
BMOU4474400	DENT	RIGHT
MSKU5630986	DENT	CORNER
MSKU5630986	DENT	CORNERPOST

FOR RECEIPT ONLY
 WITHOUT ANY PREJUDICE
 CONTAINER NOT SHOWN
 TO DUTY OFFICER

MAERSK NAKURU *Author*
 OFF HK-3605 Call Sign VRKZ8
 POR: HONG KONG 216
 GRT: 25,904 BHP: 29,200

Without any liability accepted
 Constanta South Container Terminal
 Planning Department

Container	Damage type	Damage location
MSKU5630986	DENT	LEFT
MRKU9869241	DENT	LEFT
MSKU3684828	BENT	RIGHT
SUDU7591157	DENT	LEFT
SUDU1399131	IMO LABEL	RIGHT
MSKU5083071	DENT	RIGHT
SUDU6823854	BENT	RIGHT
HASU4356470	DENT	DOORSYSTEM
MAEU4656606	CUT	TARPAULIN
SEKU4636648	DENT	RIGHT
SEKU4636648	DENT	LEFT
MSKU3674943	CUT	RIGHT
MRKU4061142	DENT	LEFT
MNBU9006528	DENT	LEFT

Without any liability accepted
 Constanta South Container Terminal
 Planning Department

FOR RECEIPT ONLY
 WITHOUT ANY PREJUDICE
 CONTAINER NOT SHOWN
 TO DUTY OFFICER

MAERSK NAKURU
 OFF HK-3605 Call Sign VRKZ8
 POR: HONG KONG
 GRT: 25,904 BHP: 29,200