

DAMAGE REPORT

Inbound carrier: MAERSK NAKURU

MNKR331S

331S

06-Aug-2023 03:51

Container	Damage type	Damage location
MRKU9363084	CUT	RIGHT
SUDU7984750	CUT	FRONT
MRKU7301925	HOLE	RIGHT
MSKU3010081	DENT	LEFT
MSKU7034604	BENT	RIGHT
MSKU7034604	DENT	LEFT
MRKU7031603	DENT	LEFT
MRKU7031603	BENT	RIGHT
MSKU1714374	HOLE	TOPROOF
GLDU5451965	DENT	LEFT
GLDU5451965	DENT	RIGHT
MRKU4056423	DENT	RIGHT
MRKU4056423	DENT	LEFT
MRKU4197930	BENT	LEFT
MRKU4197930	DENT	LEFT
MRSU3314871	DENT	LEFT
MRKU8596081	DENT	CORNER
AXIU1624287	HOLE	TOPROOF
MRKU8945563	BENT	BOTTOM
MRKU6849848	DENT	LEFT
MSKU7666123	DENT	RIGHT
SUDU7772751	BENT	LEFT
MRKU7175508	BENT	BOTTOM
MRKU8927894	DENT	CORNER
DRYU9553587	DENT	LEFT
SUDU6856117	BENT	LEFT
SUDU6856117	BENT	BOTTOM
MNBU4379318	DENT	LEFT

MAERSK NAKURU
OFF HK-3605 Call Sign VRKZ8
POR: HONG KONG
GRT: 25,904 BHP: 29,200

*Discharge
as loaded*

Container	Damage type	Damage location
SUDU8515336	DENT	FRONT
SUDU8515336	DENT	RIGHT
MRKU3684929	DENT	LEFT
TCNU7772296	DENT	TOPROOF
TCNU7772296	DENT	LEFT
TCKU7133120	DENT	RIGHT
MNBU3597681	DENT	TOPROOF
MNBU3597681	DENT	CORNERPOST
TCNU7892959	DENT	LEFT
GCXU5578530	DENT	RIGHT
GCXU5578530	DENT	LEFT
GCXU5578530	BENT	LEFT
MSKU1836670	DENT	RIGHT
MNBU3794314	HOLE	TOPROOF
TCNU2430618	DENT	CORNERPOST
MIEU3061560	DENT	LEFT
MNBU0056180	DENT	LEFT
MNBU3531642	BENT	LEFT
SUDU8037047	HOLE	TOPROOF
MRKU8954924	BENT	BOTTOM
MRKU8954924	BENT	FRONT
SUDU7522069	BENT	BOTTOM
GCXU5550574	BENT	RIGHT
BSIU9846980	DENT	RIGHT
BSIU9846980	BENT	RIGHT
BSIU9846980	DENT	LEFT
BSIU9846980	BENT	LEFT
BSIU9846980	HOLE	LEFT
MRKU0943754	DENT	CORNERPOST
TCLU5643604	BENT	LEFT
MSKU0108011	BENT	LEFT
MRKU5706586	DENT	RIGHT
MRSU6351185		DOOR
MRKU3925630		RIGHT

MAERSK NAKURU
OFF HK 2505 Call Sign VRKZ8
POR: HONG KONG
GRT: 25,904 BHP: 29,200
Discharge as Loaded

Without any liability accepted
Constantia Page 2 of 6
Planning Department

Container	Damage type	Damage location
MRKU7202434	BENT	BOTTOM
MRKU7202434	DENT	LEFT
MSKU7011419	BENT	BOTTOM
MSKU7011419	DENT	LEFT
SUDU7884047	DENT	RIGHT
SUDU7884047	BENT	LEFT
MSKU1464681	DENT	LEFT
MRKU2872942	DENT	LEFT
MRSU5545329	DENT	RIGHT
HASU1119412	BENT	BOTTOM
GESU3846656	BENT	BOTTOM
GESU5523077	DENT	RIGHT
MSKU5649770	DENT	RIGHT
MSKU5649770	DENT	LEFT
MSKU5649770	BENT	BOTTOM
MSKU7629829	DENT	CORNERPOST
SUDU1496635	DENT	RIGHT
HASU4970771	BENT	LEFT
TCKU1149216	DENT	LEFT
TCKU1074082	DENT	RIGHT
MSKU2731519	DENT	RIGHT
MSKU8754717	BENT	LEFT
MRKU2063336	DENT	RIGHT
MRKU2063336	DENT	LEFT
MRKU2063336	BENT	LEFT
MSKU0257606	BENT	RIGHT
MSKU0257606	DENT	LEFT
MSKU7441404	DENT	RIGHT
MNBU3693833	DENT	LEFT
MRSU3729435	DENT	LEFT
MRSU3729435	BENT	LEFT
MSKU5538490	DENT	RIGHT
MSKU5538490	BENT	LEFT
MSKU5538490	DENT	LEFT

*Discharge as
Laad*

MAERSK NAKURU
OFF HK-3605 Call Sign VRKZ8
POR: HONG KONG
GRT: 25,904 BHP: 29,200

Without any liability accepted
Page 3 of 6
Constantia South Container Terminal
Planning Department

Container	Damage type	Damage location
MSKU1482155	BENT	LEFT
MSKU9726690	BENT	LEFT
GCXU5777948	BENT	RIGHT
MRKU2497203	BENT	LEFT
MRKU2530277	BENT	LEFT
MRKU0551856	DENT	LEFT
MRKU9212895	DENT	LEFT
MRKU9212895	DENT	CORNERPOST
MSKU7311524	DENT	LEFT
MSKU7765532	BENT	BOTTOM
MSKU3926691	BENT	BOTTOM
MSKU3926691	DENT	CORNERPOST
MSKU0879240	HOLE	TOPROOF
MSKU7908823	DENT	CORNERPOST
MIEU0038294	DENT	CORNERPOST
MRSU4049216	BENT	LEFT
MRKU4289235	DENT	RIGHT
TLLU1198690	DENT	LEFT
MSWU0035343	DENT	TOPROOF
MSWU0035343	DENT	LEFT
MRSU6214027	BENT	LEFT
MNBU9103739	DENT	CORNERPOST
HASU5055044	BENT	LEFT
MWCU6999325	DENT	LEFT
MRKU9631891	DENT	RIGHT
TCLU1748891	DENT	LEFT
MRKU9679051	DENT	CORNERPOST
MRKU9679051	TORN	CORNER
MRKU9679051	DENT	RIGHT
MNBU3189118	DENT	RIGHT
MNBU3189118	DENT	LEFT
MNBU4246450	LEAK	DOOR
ZCSU8890446	DENT	LEFT
SUDU5220100	DENT	LEFT

MAERSK NAKURU
OFF HK-3605 Call Sign VRKZ8
POR: HONG KONG
GRT: 25,904 BHP: 29,200

Discharge as loaded

Without any liability accepted
Constanta South Container Terminal
Planning Department
Page 4 of 6

Container	Damage type	Damage location
SUDU5220100	DENT	RIGHT
MRKU2002198	DENT	CORNERPOST
MRKU4037260	BENT	RIGHT
MRKU4037260	DENT	RIGHT
MNBU3059259	HOLE	RIGHT
MNBU3059259	DENT	LEFT
MSKU0543636	BENT	LEFT
MSKU0543636	BENT	BOTTOM
MSKU3454825	DENT	LEFT
MSKU7730639	DENT	RIGHT
TCNU4681530	BENT	RIGHT
GESU5749655	DENT	RIGHT
GESU5749655	BENT	RIGHT
GESU5749655	DENT	LEFT
MRKU2478986	DENT	RIGHT
MRKU2691100	DENT	FRONT
TLLU2467557	DENT	FRONT
MRKU8807456	DIRTY	LEFT
CAAU6080492	BENT	LEFT
MRKU0226537	DENT	LEFT
TRLU6422459	CUT	TARPAULIN
TRHU6534532	DENT	LEFT
BEAU5009646	DENT	FRONT
BEAU5009646	DENT	LEFT
MNBU0594610	BENT	LEFT
MRSU4806900	DENT	RIGHT
MRKU3315350	DENT	LEFT
MSKU1027845	BENT	LEFT
BSIU8109802	DENT	TOPROOF
HASU4694436	DENT	LEFT
MRSU5625002	BENT	LEFT
MRKU8229086	DENT	RIGHT
MSKU7824804	DENT	LEFT
MSKU7824804	DENT	RIGHT

MAERSK NAKURU
OFF HK-3605 Call Sign VRKZ8
POR: HONG KONG
GRT: 25,904 BHP: 29,200

*Discharge as
Loaded*

Without any liability accepted
Constantia South Container Terminal
Planning Department

Container	Damage type	Damage location
HASU1481930	DENT	CORNER
MRKU7116784	DENT	RIGHT
MSKU4089250	DENT	RIGHT
MRSU5251704	DENT	LEFT
MRSU5587936	DENT	DOORSYSTEM
HASU1495385	DENT	LEFT
SUDU7586295	DENT	RIGHT
SUDU7586295	BENT	RIGHT
MSKU4149071	DENT	CORNERPOST
MSKU4149071	DENT	CORNER
PONU2009614	DENT	RIGHT
PONU2009614	BENT	RIGHT
PONU8238840	DENT	LEFT
SKHU9816576	DENT	RIGHT
BMOU2290657	BENT	BOTTOM
MRKU6163610	DENT	LEFT
MSKU7323628	BENT	BOTTOM
MSKU2796443	DENT	RIGHT
MSKU2796443	BENT	BOTTOM
MRKU8021261	BENT	BOTTOM
SUDU7753896	BENT	BOTTOM
SUDU7753896	DENT	RIGHT
SUDU7753896	DENT	LEFT
SUDU7753896	BENT	LEFT

MAERSK NAKURU
OFF HK-3605 Call Sign VRKZ8
POR: HONG KONG
GRT: 25,904 BHP: 29,200

Discharge as Loaded

Without any liability accepted
Constanta South Container Terminal
Planning Department

Page 6 of 6