

DAMAGE REPORT

Inbound carrier: SAFMARINE NUBA
NUBA301S 301S 09-Jan-2023 06:31

Container	Damage type	Damage location
MRKU9983526	BENT	LEFT
MRKU8096281	BENT	LEFT
TCLU8154680	DENT	LEFT
SUDU6184080	DENT	RIGHT
HLXU6511416	DENT	LEFT
MRKU9493149	BENT	LEFT
CAAU6569903	DENT	RIGHT
TCKU7031010	DENT	RIGHT
CAXU6980544	BENT	LEFT
MSKU0869659	CUT	TOPROOF
MSKU0449189	DENT	RIGHT
MSKU0449189	DENT	LEFT
TRHU7114935	DENT	RIGHT
TGHU9848833	HOLE	TOPROOF
MRKU3575297	DENT	RIGHT
MRKU3575297	DENT	LEFT
MSKU0855531	DENT	RIGHT
MSKU5634209	BENT	LEFT
MSKU4157919	DENT	LEFT
MRKU7568001	BENT	LEFT
BSIU9455477	DENT	RIGHT
MSKU5947121	BENT	FRONT
MSKU5947121	BENT	LEFT
TRHU4628674	DENT	RIGHT
TRHU4628674	DENT	LEFT
MRKU8644430	DENT	LEFT
MRKU8626020	DENT	RIGHT
TCLU6181650	DENT	LEFT

SAFMARINE NUBA
OFF. NO.: HK-3610
HONG KONG
CALL SIGN: VRLA5
GT: 25,904
BHP: 29,200

Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
AMFU8740028	BENT	RIGHT
AMFU8740028	BENT	LEFT
AMFU8740028	DENT	BOTTOM
MRSU4350997	BENT	LEFT
MRSU4350997	DENT	RIGHT
MRSU4350997	DENT	BOTTOM
MRKU7874845	DENT	LEFT
SUDU5130691	BENT	RIGHT
SUDU5130691	DENT	RIGHT
SUDU5130691	BENT	LEFT
FCIU9082519	BENT	LEFT
INBU3869390	DENT	CORNER
MNBU0004550	BENT	RIGHT
MNBU0004550	DENT	RIGHT
HASU1023244	DENT	LEFT
MSKU5406826	DENT	CORNER
MAEU4155630	CUT	TARPAULIN
MRKU4277492	BENT	RIGHT
MRKU4277492	DENT	RIGHT
MRKU4277492	BENT	LEFT
MRKU0844010	BENT	LEFT
MMAU1248716	RIP	CABLE
MRKU0159845	DENT	LEFT
MRKU0803963	DENT	FRONT
MSKU3167846	BENT	RIGHT
MRKU2287357	DENT	LEFT
MSKU9314815	BENT	RIGHT
TCLU5643538	DENT	LEFT
MRKU2579195	DENT	LEFT
MRKU8129908	DENT	CORNERPOST
MRKU8129908	DENT	RIGHT
SUDU8961699	DENT	LEFT
MSKU5838136	DENT	CORNERPOST
MSKU5838136	DENT	CORNER

SAFMARINE NUBA
OFF. NO.: HK-3610
HONG KONG
CALL SIGN: VBA45
GT: 25,904
BHP: 29200

Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
BEAU5814748	DENT	RIGHT
MRSU4128357	DENT	LEFT
MRSU4128357	DENT	RIGHT
PONU8095820	BENT	LEFT
MRKU9220972	BENT	RIGHT
MRKU9220972	DENT	RIGHT
MSKU1814706	DENT	LEFT
MSKU3971704	DENT	LEFT
MRKU7684104	DENT	LEFT
MRSU0221266	BENT	LEFT
HASU5120704	DENT	LEFT
MRKU9058408	DENT	LEFT
TGHU9217817	DENT	RIGHT
TGHU9217817	BENT	LEFT
MRKU8686631	BENT	RIGHT
MRKU8686631	BENT	LEFT
HASU1362356	DENT	LEFT
SUDU8505600	DENT	LEFT
CXDU1958205	DENT	RIGHT
MSKU1243206	DENT	RIGHT
MRSU3376066	BENT	LEFT
TCNU7072944	DENT	LEFT
GCXU5703544	BENT	LEFT
GCXU5703544	DENT	LEFT
MRSU5929345	DENT	LEFT
MRKU4346778	DENT	LEFT
MRSU5211342	DENT	RIGHT
MRSU5211342	CUT	FRONT
MSKU4249532	DENT	LEFT
CAAU6514454	DENT	LEFT
MSKU0721661	DENT	LEFT
CAAU5126990	HOLE	TOPROOF
MSKU6326664	DENT	LEFT
MRKU5374922	BENT	LEFT

SAFMARINE NUBA
OFF. NO.: HK-3610
HONG KONG
CALL SIGN: VRLA5
GT: 25,904
GHP: 29,200

Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
MRKU5061342	DENT	LEFT
MRKU5061342	DENT	CORNERPOST
MRKU5061342	DENT	FRONT
MRKU7254320	BENT	TOPROOF
MRKU7254320	DENT	TOPROOF
MRKU7254320	DENT	RIGHT
MRKU7254320	DENT	CORNERPOST
HASU4153175	DENT	LEFT
MRKU6909802	BENT	LEFT
MAEU4188640	CUT	TARPAULIN
MRKU9147510	DENT	RIGHT
MRKU9147510	DENT	CORNERPOST
MRKU8600366	DENT	CORNERPOST
MRKU8600366	DENT	RIGHT
MRKU8600366	DENT	CORNER
TGHU9692606	DENT	LEFT
TRHU4039653	DENT	LEFT
HASU4011674	DENT	RIGHT
HASU4011674	DENT	LEFT
MRKU7031060	DENT	RIGHT
MRKU7031060	DENT	CORNERPOST
MRKU7031060	TORN	CORNER
IPXU3999809	DENT	FRONT
TGBU8926570	BENT	RIGHT
SUDU5195650	DENT	LEFT
SUDU5195650	DENT	BACK
SUDU6227773	BENT	LEFT
SUDU6227773	DENT	LEFT
HASU1084614	DENT	LEFT
TEMU7966901	DENT	LEFT
MNBU0102984	DENT	LEFT
PONU1852964	DENT	LEFT

SAFMARINE NUBA
OFF. NO.: HK-3610
HONG KONG
CALL SIGN: VRLA5
G.P. 25,904
B.H.F. 29,200
DISPATCHED
LOM

Without any liability accepted
Constanta South Container Terminal
Planning Department