


External audits show progress

Sine Maersk - Plot 8-9 (Sök Denizcilik) audit status (No. of findings):



Note:

1. The Sine Maersk, largest container ship ever and our first EU-flagged has undergone EU Ship Recycling Regulation compliant recycling at Plot 8-9 (Sök Denizcilik)
2. For HSE audits conducted by Class Lloyd's Register (LR), the final report includes 'observation', which reflects deviance from best practices and provide Class LR's view, but is as such not a non-compliance to Maersk RSRS. There was 9 observation at the end of the recycling of the subject vessel
3. The external audit progress demonstrates that engagement on the ground leads to swift improvements related to RSRS compliance

There were no open critical findings or major non-conformances at the time of commencement of ship recycling operations of Sine Maersk at Plot 8-9 (Sök Denizcilik), Aliaga