

DAMAGE REPORT

Inbound carrier: SAFMARINE

SNKR042S 042S

17-Oct-2020 23:06

Container	Damage type	Damage location
MRKU4579759	DENT	RIGHT
PONU0092738	DENT	DOOR
TRLU8042170	DENT	RIGHT
MRKU0902673	DENT	RIGHT
PONU1822830	DENT	LEFT
MSKU1536143	DENT	RIGHT
MRKU8422650	TORN	DOORSYSTEM
MRKU3754100	DENT	LEFT
MRKU3754100	DENT	CORNERPOST
MSKU1433401	BENT	RIGHT
MSKU9375301	DENT	LEFT
TCNU9395714	DENT	LEFT
MRSU4087495	DENT	FRONT
PONU7156876	DENT	RIGHT
MRSU4030205	DENT	LEFT
MRSU3326764	BENT	RIGHT
MRSU3326764	BENT	LEFT
TCLU7031737	CUT	TARPAULIN
MRKU5953605	CUT	LEFT
MRKU5953605	BENT	LEFT
MRKU3787932	DENT	FRONT
HASU4551266	DENT	CORNERPOST
MRKU3480421	BENT	LEFT
MRKU3480421	DENT	LEFT
HASU4631000	DENT	LEFT
SEGU4320151	BENT	LEFT
MSKU8775303	DENT	RIGHT
PONU7859800	DENT	RIGHT

Without any liability accepted
Constanta South Container Terminal
Planning Department
Page 1 of 3

Container	Damage type	Damage location
MRSU3514170	BENT	LEFT
MVIU0012178	BENT	RIGHT
MVIU0012178	DENT	LEFT
MSKU0830889	DENT	RIGHT
MRKU7352774	BENT	LEFT
MRKU7352774	DENT	LEFT
MSKU5827975	DENT	CORNERPOST
MSKU5827975	CUT	FRONT
MSKU5827975	DENT	FRONT
MSKU5827975	DENT	RIGHT
MSKU5827975	BENT	RIGHT
TCNU1932946	BENT	RIGHT
MRKU5654266	DENT	FRONT
MRKU2430621	HOLE	FRONT
MSKU5822530	IMO LABEL	LEFT
MSKU5822530	IMO LABEL	BACK
MSKU6608009	CUT	RIGHT
PONU0030356	IMO LABEL	BACK
MRKU8331400	DENT	CORNER
MRKU7415933	DENT	LEFT
MRKU0084160	DENT	RIGHT
MRKU5161444	DENT	RIGHT
MSKU1101480	DENT	LEFT
MRKU2753183	BENT	RIGHT
SUDU7937635	DENT	LEFT
MRSU4112704	DENT	RIGHT
MRKU6634069	DENT	FRONT
MRKU6634069	DENT	BOTTOM
MRKU3738542	DENT	LEFT
MSKU5649256	CUT	RIGHT
MSKU5649256	BENT	RIGHT
MRKU0211769	BENT	LEFT
HASU4137580	DENT	RIGHT
SUDU6729703	DENT	RIGHT

Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
MSKU9456511	DENT	RIGHT
MSKU8523240	DENT	LEFT

Without any liability accepted
Constanta South Container Terminal
Planning Department