

DAMAGE REPORT

Inbound carrier: ALEXANDER

ALXR137E

137E

19-Sep-2021 21:28

Container	Damage type	Damage location
MRSU3765279	IMO LABEL	FRONT
MRSU3765279	DENT	RIGHT
SUDU7637140	DENT	CORNER
TCNU5290870	BENT	LEFT
TCNU5290870	BENT	RIGHT
CAIU4991297	DENT	RIGHT
MRKU4130393	HOLE	TOPROOF
TCNU2854180	BENT	LEFT
CAAU6634418	CUT	LEFT
MSKU3765853	LEAK	CORNER
MSKU3115694	BENT	FRONT
MRKU9880106	BENT	LEFT
CXSU1024161	CUT	TARPAULIN
SUDU7780649	DENT	LEFT
SEGU7310373	CUT	TARPAULIN
SJKU4418162	CUT	TARPAULIN
MSKU1570889	BENT	RIGHT
MRSU5040569	BENT	LEFT
SCMU4030196	DENT	RIGHT
TLLU2241472	DENT	LEFT
MRKU7753930	BENT	RIGHT
MRKU7753930	BENT	LEFT
MRKU2598071	DENT	RIGHT
CXSU1012514	CUT	TARPAULIN
CRTU7405084	CUT	TARPAULIN
SUDU1484927	DENT	CORNER
MSKU2370822	DENT	LEFT
SUDU7970232	DENT	CORNER



M.V. ALEXANDER MAERSK

Without any liability
 DP World Constanta
 Page 1 of 2
 19/09/2021

