

DAMAGE REPORT

Inbound carrier: JPO SCORPIUS

SCRP102S

102S

15-Jan-2021 02:05

Container	Damage type	Damage location
CAAU5204710	DENT	LEFT
PONU8156280	DENT	RIGHT
PONU8156280	BENT	RIGHT
MSKU5495253	DENT	RIGHT
MRKU2949828	TORN	DOORSYSTEM
TEMU6333730	HOLE	TOPROOF
MSKU0125472	DENT	RIGHT
MSKU5144536	DENT	RIGHT
MSKU1171282	BENT	LEFT
MSKU1171282	BENT	RIGHT
TGBU9348100	HOLE	TOPROOF
MSKU0293408	DENT	LEFT
MSKU0293408	DENT	RIGHT
MNBU0042020	HOLE	TOPROOF
MIEU0009830	DENT	LEFT
TCKU1973663	DENT	RIGHT
SUDU8880534	BENT	FRONT
UESU4635796	DENT	BACK
SUDU6896212	DENT	LEFT
MSKU1562950	DENT	LEFT
MIEU3067022	DENT	LEFT
XINU8157851	DENT	LEFT
MRKU8799788	DENT	LEFT
MRKU0780600	HOLE	FRONT
MRKU6314975	DENT	RIGHT
MSKU0870731	DENT	RIGHT
MSKU1519552	DENT	LEFT
MRKU4961421	DENT	RIGHT

LEFT any liability accepted
Constanta South Container Terminal
Planning Department

SCR102S

102S

15-Jan-2021 02:05

Container

Damage type

Damage location

MRKU4622808

BENT

RIGHT

BEAU5208015

DENT

LEFT

PONU7851477

DENT

LEFT

Without any liability accepted
Constanta South Container Terminal
Planning Department