

### DAMAGE REPORT

Inbound carrier: JULIUS S

JULS105 105S

07-Feb-2021 17:33

Container	Damage type	Damage location
MSKU0890065	DENT	LEFT
MSKU9212808	DENT	LEFT
MRKU5527261	DENT	LEFT
MSKU6342367	BENT	LEFT
MSKU1537509	DENT	LEFT
TLLU5845692	DENT	RIGHT
TRIU0300485	CUT	TARPAULIN
SUDU9800087	CUT	TARPAULIN
MAEU4074020	CUT	TARPAULIN
MSKU0437911	DENT	RIGHT
SUDU6683789	BENT	LEFT
TLLU4773915	DENT	LEFT
TCLU5015280	DENT	LEFT

Without any liability accepted  
Constanta South Container Terminal  
Planning Department

