

DAMAGE REPORT

Inbound carrier: JULIUS S

JULS111S 111S

18-Mar-2021 15:22

Container	Damage type	Damage location
MSKU4104246	DENT	CORNERPOST
MSKU4104246	DENT	CORNER
MRKU3053435	DENT	RIGHT
MRKU3053435	DENT	CORNERPOST
MRKU2410965	DENT	RIGHT
MNBU3348375	DENT	BOTTOM
MSKU0722349	CUT	DOOR
MSKU0722349	HOLE	DOOR
TLLU5395738	DENT	LEFT
TLLU5395738	DENT	RIGHT
TRHU2197177	DENT	LEFT
TCLU8720854	BENT	FRONT
MRKU5077800	DENT	RIGHT
MRKU5077800	BENT	LEFT
MRKU5077800	DENT	LEFT
MRSU4177578	DENT	RIGHT
MRSU4177578	DENT	LEFT
MSKU3502836	CUT	FRONT
MIEU3056429	DENT	LEFT
MSKU5920157	HOLE	TOPROOF
MSKU7662534	BENT	BOTTOM
MSKU5993750	DENT	RIGHT
HASU4464536	BENT	LEFT
HASU5085500	DENT	LEFT
MRSU3068443	CUT	RIGHT
MRSU3901061	DENT	LEFT
TCLU9920142	DENT	LEFT
MRKU9178039	BENT	BOTTOM

Without any liability accepted
Constanta South Container Terminal
Planning Department

[Signature]

Container	Damage type	Damage location
MRKU3267904	DENT	LEFT
MSKU4480794	BENT	BOTTOM
MRKU8770336	DENT	CORNER
MSKU9450386	DENT	BOTTOM
MSKU9450386	BENT	LEFT
MSKU9450386	BENT	RIGHT
MSKU0753545	DENT	LEFT
MSKU0753545	BENT	LEFT
MRKU9100386	BENT	LEFT
MRKU3929678	DENT	RIGHT
MRKU6485200	DENT	RIGHT
MSKU6774801	DENT	CORNERPOST
SUDU8633663	BENT	RIGHT
MSKU9273568	DENT	RIGHT
MSKU9273568	BENT	RIGHT
SUDU6566421	BENT	LEFT
SUDU6566421	DENT	LEFT
PONU8128170	DENT	LEFT
PONU8228076	DENT	LEFT
PONU8228076	BENT	LEFT
TRIU0319578	CUT	TARPAULIN
GLDU5518272	DENT	LEFT
MSKU9460759	DENT	CORNERPOST

Without any liability accepted
Toronto South Container Terminal
Planning Department

[Signature]