

DAMAGE REPORT

Inbound carrier: JULIUS S

JULS123S 123S

10-Jun-2021 09:49

Container	Damage type	Damage location
TCLU2465978	DENT	RIGHT
MRSU4229840	DENT	FRONT
MRSU4229840	DENT	BOTTOM
MRSU4229840	CUT	BOTTOM
AXIU1617518	BENT	RIGHT
AXIU1617518	BENT	LEFT
AXIU1617518	BENT	BOTTOM
PONU0125600	DENT	LEFT
MSKU7715697	DENT	RIGHT
MSKU7715697	BENT	BOTTOM
MRKU4244673	DENT	CORNERPOST
MSKU7892835	DENT	RIGHT
MSKU7892835	DENT	LEFT
MSKU8850182	DENT	LEFT
MSKU8601451	DENT	DOORSYSTEM
MSKU8601451	DENT	FRONT
MSKU8601451	DENT	BOTTOM
MRKU4564342	BENT	LEFT
TCKU6506574	TORN	DOORSYSTEM
MRKU5207524	CUT	BACK
MRKU5207524	BENT	BACK
MRKU5207524	CUT	DOOR
MRKU3755046	CUT	FRONT
MRKU3755046	CUT	BOTTOM
MRKU3755046	DENT	FRONT
PONU1840304	DENT	FRONT
CAAU5941066	DENT	LEFT
MAEU4216464	CUT	TARPAULIN

Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
MAEU4059030	CUT	TARPAULIN
MAEU4100751	CUT	TARPAULIN
GESU3508875	TORN	DOORSYSTEM
MRKU7092960	BENT	BOTTOM
MAEU4722360	CUT	TARPAULIN
MAEU4732732	CUT	TARPAULIN
HASU4927142	BENT	LEFT
MSKU6301769	DENT	RIGHT
MSKU6301769	DENT	CORNERPOST
MRKU0715008	DIRTY	LEFT
MSKU5766817	BENT	BOTTOM
MRSU3787719	CUT	FRONT
MRSU3787719	BENT	FRONT
MRSU3787719	DENT	BOTTOM
SUDU7542023	DENT	FRONT
MRKU9019016	DENT	RIGHT
MSKU5748161	BENT	BOTTOM
PONU0546764	DENT	LEFT
MSKU7934925	BENT	BOTTOM
TRHU1766324	BENT	BOTTOM
MSKU7335090	BENT	BOTTOM
MRKU7124440	BENT	LEFT
MRKU9986274	BENT	BOTTOM
MSKU3078950	BENT	BOTTOM
TTNU5842870	BENT	BOTTOM
TTNU5842870	DENT	LEFT
MRKU0024264	DENT	LEFT
MRKU0282572	DENT	LEFT
SUDU6280551	IMO LABEL	FRONT
SUDU6280551	IMO LABEL	RIGHT
SUDU6280551	IMO LABEL	DOOR
SUDU6280551	IMO LABEL	LEFT
MRKU0135904	BENT	BOTTOM
MRKU0135904	DENT	FRONT

Without any liability accepted
 Constanta South Container Terminal
 Planning Department

Container	Damage type	Damage location
-----------	-------------	-----------------

MSKU7239029	BENT	FRONT
HASU4333515	TORN	CORNERPOST
GATU0949526	BENT	BOTTOM
MSKU2971021	DENT	DOORSYSTEM
MSKU8355300	DENT	LEFT
MAEU4078703	CUT	TARPAULIN
MAEU4107632	CUT	TARPAULIN
TCNU2432159	BENT	BOTTOM
PONU8217805	DENT	LEFT
MRKU2935418	DENT	LEFT
MAEU3456455	CUT	TARPAULIN
MAEU3469597	CUT	TARPAULIN
SUDU2842136	CUT	TARPAULIN
MAEU4692239	CUT	TARPAULIN
MSKU7128745	DENT	LEFT
MRKU0193120	BENT	BOTTOM
PONU0362129	BENT	BOTTOM
MAEU3489844	CUT	TARPAULIN
TCNU1933080	BENT	BOTTOM
TCNU1933080	BENT	LEFT
PONU8188749	BENT	LEFT
MSKU4039449	BENT	BOTTOM
MSKU4186460	CUT	DOOR
MSKU0970598	HOLE	RIGHT
MSKU0970598	CUT	RIGHT
MRKU9658399	BENT	FRONT
TCNU2480075	DENT	BACK
TCNU2480075	DENT	BOTTOM
TCNU2480075	BENT	LEFT
TCNU2480075	CUT	FRONT
TCKU7283840	DENT	LEFT
SUDU7614360	BENT	BOTTOM
HASU1443756	BENT	BOTTOM
MRKU7636641	DENT	CORNER

Without any liability accepted
 Constantia South Container Terminal
 Planning Department