

DAMAGE REPORT

Inbound carrier: JULIUS S
 JULS134N 134N 29-Aug-2021 20:48

Container	Damage type	Damage location
MRKU7290712	DENT	CORNER
HASU4437211	DENT	LEFT
HASU4437211	DENT	RIGHT
MSKU0451530	DENT	RIGHT
FCIU8322683	BENT	FRONT
TCKU7442448	DENT	LEFT
MSKU6508606	BENT	LEFT
MSKU6508606	BENT	RIGHT
TCNU2692900	DENT	RIGHT
MRKU2227764	DENT	LEFT
FCBU8699389	DENT	LEFT
MSKU5737362	DENT	LEFT
SEKU4702014	DENT	LEFT
SEKU4702014	BENT	LEFT
TGBU6016170	BENT	LEFT
TGBU6016170	BENT	RIGHT
TCLU4756484	DENT	LEFT
MRKU8576953	BENT	BOTTOM
TCKU7443254	DENT	RIGHT
MRKU8187930	BENT	LEFT
MRKU2727754	DENT	LEFT

Without any liability accepted
 Constanta South Container Terminal
 Planning Department

Ⓞ FOR RECEIPT ONLY
 Ⓞ DISCHARGED AS LOADED

do B. J.

 St. John's

STATEMENT REPORT

Vessel information:

JULIUS S 134N 29-Aug-2021 20:49

Container	Reference changed	User	Manifested Seal	Seal found
HASU1080814	unitSealNbr2	MIRONIFL	: null	MY0509369
HASU4475525	unitSealNbr2	POVARAI	: null	HM552089
MRKU2076863	unitSealNbr1	OPREAR	: AE3956750	ML RO0262282
MRKU6678806	unitSealNbr2	MIRONIFL	: null	RO0262283
MRKU6796347	unitSealNbr2	OPREAR	: null	107554
MRKU7469185	unitSealNbr2	OPREAR	: null	107595
MRKU7612212	unitSealNbr1	OPREAR	: IN3349196	PACK00802979
MRKU7985216	unitSealNbr2	OPREAR	: null	107557
MSKU3885437	unitSealNbr2	MIRONIFL	: null	PACK00802973
MSKU4226840	unitSealNbr2	MIRONIFL	: null	RO0262286
MSKU5507056	unitSealNbr2	OPREAR	: null	008541
MSKU7286437	unitSealNbr2	OPREAR	: null	107579
MSKU7610398	unitSealNbr1	OPREAR	: IN3347386	PACK00802970
PONU2009086	unitSealNbr2	MIRONIFL	: null	IN3349691
TCKU1106338	unitSealNbr1	OPREAR	: IN3349170	PACK00802974
TCKU1232125	unitSealNbr2	OPREAR	: null	107587

Without any liability accepted
Constanta South Container Terminal
Planning Department

* FOR RECEIPT ONLY
* DISCHARGED AS LOADED

St. John's