

**DAMAGE REPORT**

Inbound carrier: JULIUS S

JULS108S 108S

26-Feb-2021 11:23

Container	Damage type	Damage location
SUDU1351246	DENT	CORNERPOST
TGBU6786422	BENT	LEFT
MSKU5042745	BENT	FRONT
UETU2602781	DENT	CORNER
TGHU1706391	DENT	CORNERPOST
TGHU1706391	DENT	CORNER
MSKU9349154	DENT	LEFT
MRKU5925033	DENT	RIGHT
PONU8206518	DENT	RIGHT
TEMU3209807	DENT	LEFT
TEMU5615301	DENT	RIGHT
GESU3553046	TORN	DOORSYSTEM
MRKU4291715	DENT	LEFT
MSKU9368642	HOLE	LEFT
MRSU4062481	HOLE	LEFT
MRSU4062481	DENT	FRONT
MSKU6930524	DENT	RIGHT
MSKU8774729	DENT	LEFT
SUDU1798851	DENT	FRONT
MRKU6018870	BENT	LEFT
MRKU2566562	DENT	FRONT
CAXU8151970	DENT	RIGHT
HASU4195078	DENT	LEFT
MSKU1488596	BENT	RIGHT
MSKU1488596	DENT	RIGHT
MSKU1488596	BENT	LEFT
MSKU1488596	DENT	LEFT
MRKU0190985	DENT	RIGHT

Without any liability accepted  
Constanta South Container Terminal  
Planning Department

Container	Damage type	Damage location
MRKU2815557	DENT	RIGHT
MRSU3811190	CUT	TOPROOF
MRSU3811190	HOLE	TOPROOF
TRHU5213950	DENT	RIGHT
MIEU0030800	BENT	LEFT
MIEU0030800	DENT	LEFT
MSKU8750732	DENT	RIGHT
MSKU9607670	DENT	LEFT
PONU7981803	DENT	LEFT
FCIU8390013	HOLE	LEFT
MRKU0189201	DENT	LEFT
PONU1737770	HOLE	RIGHT
TEMU8848647	BENT	RIGHT
TRLU7614760	DENT	LEFT
FFAU1867920	BENT	LEFT
MIEU0018786	BENT	LEFT
PONU8161711	DENT	LEFT
PONU7991226	DENT	FRONT
PONU7991226	DENT	LEFT
SEKU4462926	BENT	RIGHT
SEKU4462926	BENT	LEFT

Without any liability accepted  
Constanta South Container Terminal  
Planning Department