

DAMAGE REPORT

Inbound carrier: SAFMARINE NUBA
NUBA109S 109S 04-Mar-2021 17:32

Container	Damage type	Damage location
HASU4492707	DENT	FRONT
HASU4492707	DENT	CORNERPOST
TCLU5780865	BENT	LEFT
MRKU0584572	DENT	RIGHT
SUDU5962834	BENT	RIGHT
PONU8108764	DENT	LEFT
MSKU9183680	DENT	LEFT
PONU0019151	DENT	RIGHT
TCNU6003152	DENT	RIGHT
TGHU9607796	DENT	RIGHT
MRKU5055735	DENT	RIGHT
MRKU2167840	DENT	CORNERPOST
MRKU4634964	BENT	LEFT
MRKU8259141	BENT	FRONT
TGHU7434963	BENT	LEFT
SUDU8665824	DENT	LEFT
MSKU3125455	DENT	RIGHT
MSKU8871462	BENT	RIGHT
MRKU2949221	DENT	CORNERPOST
MRKU4295813	BENT	LEFT
MRKU1069978	DENT	CORNERPOST
MRKU1069978	BENT	LEFT
MRKU4726567	DENT	RIGHT
PONU2079695	DENT	RIGHT
PONU0301421	DENT	LEFT
MSKU9139965	DENT	CORNERPOST
MSKU0430814	DENT	LEFT
MRKU8067278	BENT	BOTTOM

Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
MSKU3233249	DENT	LEFT
GATU8519429	BENT	RIGHT
MSKU3489159	DENT	RIGHT
MRSU3774429	DENT	CORNERPOST
MRKU6161876	RIP	FRONT
MRKU6161876	RIP	BOTTOM
PONU7975760	DENT	FRONT
PONU7975760	CUT	FRONT
SUDU6951264	DENT	RIGHT
UESU4557292	DENT	RIGHT
MRKU0165236	DENT	RIGHT
PONU7406131	DENT	LEFT
MSKU5263710	DENT	LEFT
TRLU6857467	BENT	FRONT
SUDU6835304	DENT	RIGHT
MRKU7929892	DENT	CORNER
MRKU7929892	DENT	CORNERPOST