

**DAMAGE REPORT**

Inbound carrier: SAFMARINE

SNKR107S 107S

18-Feb-2021 20:47

Container	Damage type	Damage location
MNBU3150543	CUT	FRONT
MAEU4219226	CUT	TARPAULIN
TCNU6108702	DENT	CORNERPOST
TRHU4380700	BENT	LEFT
MAEU4171919	CUT	TARPAULIN
MRKU4016781	BENT	FRONT
GESU5047366	DENT	LEFT
SUDU9801062	CUT	TARPAULIN
SUDU5984999	DENT	LEFT
MSKU0841651	HOLE	TOPROOF
TLLU5128372	DENT	LEFT
PONU8196493	BENT	LEFT
MAEU4120716	CUT	TARPAULIN
MRKU9927899	CUT	FRONT
TCKU1023017	DENT	LEFT
HASU1527883	DENT	CORNERPOST
PONU7453663	BENT	RIGHT
MRKU2192776	DENT	RIGHT
CAIU7231765	DENT	RIGHT
TCNU4117238	DENT	FRONT
TCNU4117238	DENT	RIGHT
MRKU0854195	DENT	DOORSYSTEM
SUDU5452086	DENT	LEFT
TGHU8887310	DENT	RIGHT
MSKU1418990	DENT	LEFT

Without any liability accepted  
Constanta South Container Terminal  
Planning Department