

DAMAGE REPORT

Inbound carrier: SAFMARINE

SNKR119S 119S

13-May-2021 08:26

Container	Damage type	Damage location
MRSU3830604	DENT	FRONT
UESU4562679	DENT	CORNERPOST
HASU1551576	DENT	LEFT
TCNU1832989	BENT	LEFT
MNBU3316280	DENT	RIGHT
MIEU3075964	DENT	LEFT
MSKU2041811	DENT	LEFT
MSKU1714944	BENT	RIGHT
HASU4909750	DENT	RIGHT
MNBU3975523	TORN	DOORSYSTEM
TTNU1247082	DENT	RIGHT
MSKU7292656	DENT	BOTTOM
MSKU9439319	BENT	RIGHT
MSKU8320855	HOLE	FRONT
MSKU9526706	DENT	RIGHT
MSKU9526706	BENT	RIGHT
MRKU2957654	DENT	LEFT
SUDU5142877	BENT	RIGHT
SUDU5142877	DENT	LEFT
MRKU6363856	DENT	RIGHT
MNBU3047371	DENT	FRONT
MNBU3047371	CUT	FRONT
MNBU3047371	CUT	BOTTOM
MNBU3047371	HOLE	BOTTOM
MSWU9039545	CUT	RIGHT
MSWU9039545	CUT	TOPROOF
MSWU9039545	DENT	TOPROOF
MSWU9039545	DENT	RIGHT

Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
MWCU6986837	DENT	TOPROOF
TCLU5753664	DENT	FRONT
MRKU2225864	DENT	RIGHT
MRKU4189787	RUSTED	DOORSYSTEM
MRSU3898800	DENT	RIGHT
MRSU3898800	DENT	LEFT
TRLU7550006	HOLE	FRONT
MRKU4565307	BENT	RIGHT
MRKU4565307	BENT	LEFT
MWMU6426853	HOLE	TOPROOF
MSKU8028627	DENT	LEFT
MRKU8021934	DENT	LEFT
HASU1013673	DENT	RIGHT
TLLU4893232	BENT	LEFT
UETU5038783	BENT	RIGHT
SEGU4379083	BENT	RIGHT
TCNU7755750	BENT	LEFT
CRSU1488241	BENT	LEFT
MRKU0672740	BENT	LEFT
TEMU7802575	BENT	FRONT
MRKU7097180	DENT	CORNERPOST
MRKU6958047	DENT	CORNERPOST
MRKU4051550	DENT	RIGHT

~~Without any liability accepted
Constanta South Container Terminal
Planning Department~~