

DAMAGE REPORT

Inbound carrier: SAFMARINE

SNKR122S 122S

03-Jun-2021 14:54

Container	Damage type	Damage location
TGHU0135317	DENT	RIGHT
TRLU8055054	HOLE	TOPROOF
MSKU8634970	BENT	LEFT
MSKU8634970	BENT	RIGHT
HASU4710706	DENT	LEFT
MAEU3402649	CUT	TARPAULIN
MAEU3414948	CUT	TARPAULIN
MRKU3058078	DENT	RIGHT
CZZU0440608	HOLE	TOPROOF
TGBU8886122	DENT	LEFT
MAEU3402593	CUT	TARPAULIN
MRKU6071010	DENT	RIGHT
MRKU6071010	BENT	RIGHT
MRKU6071010	HOLE	FRONT
TCKU7264747	DENT	LEFT
MSKU7480972	BENT	RIGHT
MSKU7480972	BENT	LEFT
MSKU0709645	BENT	RIGHT
MSKU9985285	DENT	RIGHT
MSKU7078562	DENT	RIGHT
MSKU7078562	HOLE	TOPROOF
HASU1197821	DENT	LEFT
MRKU7328736	DENT	RIGHT
MRKU5838807	DENT	RIGHT
MRKU5838807	TORN	DOORSYSTEM
MRKU5838807	BENT	LEFT
MSKU1286316	RIP	FRONT
SUDU8974206	BENT	LEFT

Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
-----------	-------------	-----------------

MSKU0035126	DENT	LEFT
MSKU0035126	BENT	LEFT
MWCU6715959	BENT	LEFT
MWCU6715959	BENT	RIGHT
MSKU9484365	BENT	RIGHT
MSKU9484365	BENT	LEFT
MRKU7575021	DENT	LEFT
MIEU2012200	BENT	LEFT
TCNU8343228	DENT	LEFT
TCKU6172008	DENT	LEFT
MSKU8743395	DENT	LEFT
MRKU4072569	HOLE	TOPROOF
MRKU3190850	DENT	CORNERPOST
TCKU1080188	BENT	LEFT
MSKU8661682	BENT	RIGHT
MSKU8661682	DENT	LEFT
MAEU3487230	CUT	TARPAULIN
MAEU3485833	CUT	TARPAULIN
MSKU9423708	DENT	LEFT

Without any liability accepted
Constanta South Container Terminal
Planning Department