

DAMAGE REPORT

Inbound carrier: SAFMARINE NUBA
 NUBA112S 112S 26-Mar-2021 03:54

Container	Damage type	Damage location
MWCU6771989	DENT	LEFT
MSKU5462542	DENT	CORNERPOST
MSKU5462542	CUT	FRONT
MSKU5462542	CUT	BOTTOM
MSKU5462542	DENT	RIGHT
MSKU5462542	DENT	BOTTOM
GLDU5443532	DENT	RIGHT
MSKU2588748	BENT	BOTTOM
MRSU0269594	BENT	BOTTOM
MRKU6891051	BENT	BOTTOM
PONU0483579	DENT	LEFT
MSKU4477424	DENT	LEFT
MAEU6987671	DENT	LEFT
HASU5005085	DENT	LEFT
HASU5005085	BENT	LEFT
MRSU3317628	DENT	RIGHT
MRKU3206473	DENT	CORNERPOST
MSKU4214290	DENT	FRONT
TEMU3302099	DENT	LEFT
MSKU6115070	DENT	RIGHT
MRKU3429780	DENT	RIGHT
MRKU3429780	DENT	LEFT
MRKU6970063	BENT	BOTTOM
MRKU8839200	IMO LABEL	FRONT
MSKU1581013	DENT	RIGHT
HASU4271840	DENT	LEFT
HASU4271840	DENT	CORNERPOST
MRKU1082223	BENT	BOTTOM

Without any liability accepted
 Constanta South Container Terminal
 Planning Department

Container	Damage type	Damage location
MRKU1082223	BENT	RIGHT
MRKU0946368	DENT	RIGHT
MRKU7243520	BENT	BOTTOM
MSKU5228534	DENT	LEFT
MRKU2933159	DENT	RIGHT
MIEU2016946	BENT	LEFT
PONU0314331	TORN	DOORSYSTEM
MSKU6980438	DENT	LEFT
HASU4232799	BENT	BOTTOM
HASU4232799	BENT	LEFT
MRKU1078861	DENT	RIGHT
SUDU5326160	DENT	LEFT
MRKU8104129	DENT	LEFT
SUDU1323563	DENT	LEFT
SUDU6255190	LEAK	DOOR
MRKU7270399	BENT	BOTTOM
MRKU3820780	DENT	RIGHT
MRKU0031221	DENT	RIGHT
MRSU3942266	DENT	LEFT
PONU2015685	BENT	BOTTOM
HASU1414629	DENT	CORNER
PONU0517370	IMO LABEL	FRONT

Without any liability accepted
Constanta South Container Terminal
Planning Department