

DAMAGE REPORT

Inbound carrier: SAFMARINE NUBA
NUBA115S 115S 15-Apr-2021 05:47

Container	Damage type	Damage location
MRSU3926270	DENT	LEFT
MWCU6708327	DENT	LEFT
MWCU6708327	DENT	TOPROOF
PONU0603015	DENT	BOTTOM
MRKU9181330	BENT	BOTTOM
CAIU4624368	DENT	LEFT
MSKU2928940	DIRTY	DOOR
MSKU2928940	DIRTY	BACK
MRKU8696007	DENT	RIGHT
SUDU8608450	DENT	LEFT
SUDU8608450	BENT	LEFT
SUDU8608450	BENT	RIGHT
SUDU8608450	DENT	RIGHT
MNBU3471815	DENT	LEFT
MSKU2206629	BENT	LEFT
MSKU3303351	DENT	LEFT
SUDU5120707	CUT	LEFT
SUDU5120707	HOLE	LEFT
MSKU9225364	DENT	RIGHT
MSKU9225364	DENT	LEFT
MRKU4176331	DENT	LEFT
FCIU8357015	BENT	FRONT
MRSU0032880	DENT	RIGHT
APMU8055482	DENT	CORNERPOST
MNBU3847862	DENT	LEFT
MNBU0241655	BENT	LEFT
MSKU1107848	BENT	RIGHT
MSKU1107848	DENT	RIGHT

Boat Without any liability accepted
Constanta South Container Terminal
Planning Department

NUBA115S

115S

15-Apr-2021 05:47

Container	Damage type	Damage location
MSKU1107848	BENT	LEFT
MSKU1107848	DENT	LEFT
SUDU8167713	DENT	LEFT
SUDU8167713	BENT	LEFT
MMAU1167980	DENT	LEFT
CAIU2472482	DENT	CORNERPOST
MSWU0103601	DENT	LEFT
TEMU8855245	BENT	LEFT
MSKU8126393	DENT	LEFT
PONU0273660	BENT	BOTTOM
BSIU8155691	DENT	LEFT
TCNU2493133	BENT	BOTTOM
MSKU9535185	BENT	BOTTOM
MSKU9535185	BENT	LEFT
MRKU4473900	DENT	LEFT
PONU7949437	DENT	RIGHT
HASU4994541	DENT	RIGHT
HASU4873160	BENT	BOTTOM
MRKU9346723	BENT	LEFT
PONU7967533	DENT	LEFT

Boat
Without any liability accepted
Constanta South Container Terminal
Planning Department