

DAMAGE REPORT

Inbound carrier: ALEXANDER
ALXR139E 139E

02-Oct-2021 19:33

Container	Damage type	Damage location
TCNU2485550	BENT	LEFT
TCNU1707288	BENT	LEFT
MAEU3433850	CUT	TARPAULIN
MSKU5281797	DENT	CORNER
MSKU5106259	BENT	LEFT
TCKU2297814	DENT	CORNERPOST
MRSU3200755	DENT	RIGHT
PONU7643426	DENT	RIGHT
MRSU3434218	DENT	LEFT
MRKU5985500	DENT	LEFT
MAEU3431673	RIP	TARPAULIN
MRKU2903494	DENT	LEFT
MSKU1669022	DENT	CORNER
MAEU3515666	CUT	TARPAULIN
CAAU6077462	DENT	CORNERPOST
HASU4503170	DENT	RIGHT
MSKU6852524	DENT	LEFT
MRKU8132096	BENT	LEFT
MRKU2069910	DENT	LEFT
CAAU6450616	DENT	CORNERPOST
MRKU3747170	DENT	LEFT
MSKU6529609	BENT	LEFT
PONU7435567	DENT	LEFT
PONU7435567	DENT	RIGHT
MSKU6492109	BENT	LEFT
MRKU9844290	BENT	RIGHT
HASU4477620	BENT	FRONT
MSKU1471192	DENT	FRONT

Without any liability accepted
Constanta South Container Terminal
Planning Department

M.V. ALEXANDER MAERSK

