

**DAMAGE REPORT**

Inbound carrier: ALEXANDER  
ALXR141E 141E 16-Oct-2021 07:54

Container	Damage type	Damage location
MAEU4206804	CUT	TARPAULIN
CAIU6203748	BENT	BOTTOM
MRKU7421659	BENT	BOTTOM
MRSU3061921	DENT	DOOR
MRKU4993563	BENT	BOTTOM
MRKU4993563	BENT	LEFT
SUDU9711056	CUT	TARPAULIN
MAEU3487857	CUT	TARPAULIN
MSKU4486750	DENT	LEFT
MAEU4084244	CUT	TARPAULIN
SUDU5686016	BENT	BOTTOM
MAEU3422310	CUT	TARPAULIN
MAEU3454302	CUT	TARPAULIN
MRKU9615798	BENT	BOTTOM
SUDU5952311	BENT	LEFT
CAIU4826380	DENT	RIGHT
TLLU5970375	DENT	LEFT
INKU6192303	DENT	LEFT
MRKU2920320	DENT	RIGHT
MAEU3454072	CUT	TARPAULIN
MRKU6954490	BENT	BOTTOM
MRKU6954490	BENT	LEFT
UETU5920596	DENT	RIGHT
MSKU2417806	DENT	LEFT
MSKU2417806	BENT	LEFT
MAEU3503691	CUT	TARPAULIN
MRKU0576962	DENT	CORNERPOST
MRKU2185611	DENT	LEFT

Without any liability accepted  
Constanta South Container Terminal  
Planning Department

Container	Damage type	Damage location
MRKU4912129	BENT	BOTTOM
PONU8036556	BENT	BOTTOM
PONU8036556	BENT	RIGHT
TGBU9346704	BENT	RIGHT

Without any liability accepted  
Constanta South Container Terminal  
Planning Department