

DAMAGE REPORT

Inbound carrier: ALEXANDER

ALXR145E 145E

13-Nov-2021 14:50

Container	Damage type	Damage location
TCKU6775362	DENT	LEFT
MRSU5113285	DENT	LEFT
MSKU1886141	DENT	CORNER
MRKU8684053	TORN	CORNER
MRKU8684053	DENT	CORNER
MRKU5425090	DENT	LEFT
MRKU5425090	DENT	RIGHT
MRKU5675248	DENT	FRONT
SUDU7906594	HOLE	TOPROOF
MRKU5922878	DENT	LEFT
MRKU2048060	DENT	LEFT
MRKU0064354	DENT	LEFT
TCKU6621958	DENT	RIGHT
MSKU1652673	DENT	CORNERPOST
MRKU5687470	BENT	LEFT
TCKU6609741	DENT	LEFT
MRSU4207646	DENT	RIGHT
MRKU8380791	DENT	CORNER
MSKU3051136	BENT	LEFT
MSKU7834232	TORN	DOORSYSTEM
TCKU1117332	DENT	LEFT
MRSU3472624	DENT	TOPROOF
MRSU3472624	BENT	RIGHT
MRKU9124644	DENT	LEFT
GCXU5777871	BENT	LEFT
MRKU7822939	BENT	RIGHT
HASU1014622	DENT	RIGHT

Without any liability accepted
Constanta South Container Terminal
Planning Department

[Signature]
CHIEF OFFICER
M.V ALEXANDER MAERSK

Discharged as loaded w/o prejudice
SUBJECT TO OWNERS APPROVAL