

**DAMAGE REPORT**

Inbound carrier: ALEXANDER  
ALXR149E 149E

12-Dec-2021 10:25

Container	Damage type	Damage location
MRKU3938129	DENT	RIGHT
FCIU4198379	DENT	LEFT
MSKU5110290	DENT	RIGHT
MSKU5110290	DENT	LEFT
PONU1766249	DENT	RIGHT
PONU1603196	DENT	LEFT
PONU1603196	BENT	LEFT
MRKU0647855	DENT	LEFT
TCNU6275253	HOLE	FRONT
MSKU4271768	DENT	LEFT
MSKU9745052	DENT	RIGHT
MSKU2745826	DENT	RIGHT
MSKU2930640	DENT	LEFT
TCLU2280357	DENT	RIGHT
MRSU0117478	DENT	LEFT
MRKU7694205	DENT	LEFT
IPXU3172030	DENT	RIGHT
GLDU5567322	DENT	RIGHT
PONU0447247	DENT	RIGHT
MSKU3105818	DENT	LEFT
MSKU3863119	DENT	LEFT
MSKU2563863	DENT	LEFT
MSKU5275449	DENT	LEFT
PONU1795400	DENT	LEFT
MSKU7641315	DENT	RIGHT
BMOU2457826	DENT	RIGHT
MSKU1452762	DENT	RIGHT
MAEU4196769	CUT	TARPAULIN

Without any liability accepted  
Constanta South Container Terminal  
Planning Department

Container	Damage type	Damage location
MAEU4036251	CUT	TARPAULIN
PONU1883733	DENT	RIGHT
PONU1447278	DENT	LEFT
TGBU6648969	BENT	LEFT
MSKU5290058	DENT	LEFT
TRIU3932990	DENT	RIGHT
HASU5059965	BENT	RIGHT
MSKU5788415	DENT	LEFT
MRKU7071020	DENT	RIGHT
SUDU1486827	DENT	DOORSYSTEM
TCLU6627212	BENT	LEFT
CAAU5311220	BENT	LEFT
HASU4588835	DENT	LEFT
MRSU4348963	DENT	LEFT
MRKU4683568	HOLE	FRONT

Without any liability accepted  
Constanza South Container Terminal  
Planning Department Page 2 of 2