

**DAMAGE REPORT**

Inbound carrier: ALEXANDER

ALXR151E

151E

25-Dec-2021 09:50

Container	Damage type	Damage location
MRKU0876487	DENT	LEFT
MRSU4826661	HOLE	TOPROOF
MRKU5993531	DENT	LEFT
PONU8166816	DENT	RIGHT
MRSU3039698	DENT	RIGHT
TRHU4804449	DENT	LEFT
SUDU4874370	CUT	TARPAULIN
MRKU9570501	BENT	BOTTOM
MVIU0018957	DENT	RIGHT
MRKU8952407	BENT	BOTTOM
MRKU4621252	BENT	RIGHT
MAEU4129354	CUT	TARPAULIN
PONU0348624	DENT	RIGHT
TCLU2182957	DENT	LEFT
MRKU9221500	DENT	CORNER
MRKU9221500	DENT	CORNERPOST
MNBU3088600	DENT	LEFT
MRKU6763981	BENT	BOTTOM
MSKU2706033	BENT	LEFT
MSKU2706033	BENT	BOTTOM
MRSU3754865	BENT	RIGHT
HASU4501521	DENT	RIGHT
HASU4501521	DENT	LEFT
MSKU7215670	BENT	BOTTOM

Without any liability accepted  
Constanta South Container Terminal  
Planning Department