

DAMAGE REPORT

Inbound carrier: ANTWERP

ANWP144E 144E

08-Nov-2021 13:18

Container	Damage type	Damage location
MSKU7809219	DENT	FRONT
PONU8049240	DENT	LEFT
MSKU9526373	DENT	DOORSYSTEM
XINU1349852	DENT	CORNERPOST
XINU1349852	DENT	LEFT
MSKU9588992	DENT	RIGHT
TCNU1477539	DENT	LEFT
PONU0244297	BENT	LEFT
MSKU5470888	DENT	LEFT
HASU1142557	DENT	CORNERPOST
MRKU0829459	DENT	LEFT
TCKU6584582	DENT	RIGHT
CAAU6669409	BENT	LEFT
MSKU6583662	BENT	LEFT
TRHU7483044	DENT	LEFT
CAIU2406454	DENT	LEFT
MSKU0549383	BENT	FRONT
MSKU9928768	DENT	RIGHT
MRKU4188836	DENT	CORNER
MSKU8545867	DENT	LEFT
TCLU5014577	HOLE	FRONT
MSKU6889673	DENT	LEFT
TCLU2504966	DENT	LEFT
HASU4978896	DENT	RIGHT

Without any liability accepted
Constanta South Container Terminal
Planning Department