

DAMAGE REPORT

Inbound carrier: ANTWERP
ANWP146E 146E 21-Nov-2021 09:31

Container	Damage type	Damage location
MSKU5088690	TORN	DOORSYSTEM
MAEU4714180	CUT	TARPAULIN
MRKU5744689	BENT	LEFT
MRKU5744689	DENT	LEFT
MRKU5744689	BENT	RIGHT
MRKU5744689	DENT	RIGHT
MAEU4713120	CUT	TARPAULIN
MSKU8836158	DENT	LEFT
TTNU1255339	DENT	RIGHT
MAEU4682122	CUT	TARPAULIN
MAEU4190354	CUT	TARPAULIN
MRSU3326682	DENT	BOTTOM
MRKU0812754	IMO LABEL	BACK
MAEU4667220	CUT	TARPAULIN
MAEU4658234	CUT	TARPAULIN
HASU4897768	DENT	LEFT
MRKU4992280	BENT	LEFT
MRKU4992280	DENT	LEFT
TCKU7438622	DENT	LEFT
MAEU4698089	CUT	TARPAULIN
MSKU2295312	DENT	RIGHT
SUDU2850532	CUT	TARPAULIN
MRKU3941605	DENT	LEFT
SUDU2850580	CUT	TARPAULIN
MRKU3430441	BENT	FRONT
MAEU4697101	CUT	TARPAULIN
HASU1272993	DENT	RIGHT
MRKU9065500	BENT	LEFT

Without any liability accepted
Constanta South Container Terminal
Planning Department

Without any liability accepted
 Constanta South Container Terminal
 Planning Department

Container	Damage type	Damage location
MRSU5392940	BENT	LEFT
PONU1802182	DENT	LEFT
TLLU6842342	DENT	RIGHT
MAEU4677846	CUT	TARPAULIN
MRKU0014097	IMO LABEL	FRONT
MRKU0014097	IMO LABEL	BACK
MRKU0014097	IMO LABEL	LEFT
TCNU6153846	DENT	CORNER
MAEU4188700	CUT	TARPAULIN
MRKU0293221	DENT	LEFT
MSKU3342548	DENT	LEFT
MSKU6725258	DENT	RIGHT
MSKU6725258	BENT	BOTTOM
MSKU6725258	BENT	LEFT
MSKU0855022	DENT	LEFT
TCLU5280221	BENT	BOTTOM
MAEU4665830	CUT	TARPAULIN
HASU1003063	DENT	LEFT