

DAMAGE REPORT

Inbound carrier: ALEXANDER

ALXR201E 201E

08-Jan-2022 00:24

Container	Damage type	Damage location
MRKU5682864	DENT	CORNERPOST
MRKU8602923	BENT	LEFT
MRKU9116802	DENT	LEFT
MRKU6638090	BENT	BOTTOM
MRKU6638090	DENT	LEFT
PONU0922460	BENT	BOTTOM
PONU0922460	HOLE	BOTTOM
PONU0922460	TORN	BOTTOM
MSKU4290182	BENT	BOTTOM
SEKU4713868	DENT	RIGHT
MRKU2079712	DENT	LEFT
MRKU2079712	BENT	LEFT
MRKU5962757	DENT	RIGHT
MRKU5962757	BENT	RIGHT
TLLU5129743	DENT	RIGHT
SUDU8614220	DENT	CORNERPOST
TCLU6496200	IMO LABEL	FRONT
TCLU6496200	IMO LABEL	LEFT
TCLU6496200	IMO LABEL	RIGHT
MSKU1854988	BENT	FRONT
PONU0243773	DENT	CORNERPOST
TCNU1566030	BENT	RIGHT
TCNU1566030	DENT	RIGHT
MRSU4711106	HOLE	RIGHT
CAAU6547252	DENT	LEFT
HASU4218070	DENT	RIGHT
PONU8035288	BENT	LEFT

[Signature]
Without any liability accepted
Constanta South Container Terminal
Planning Department