

DAMAGE REPORT

Inbound carrier: ALEXANDER

ALXR203E 203E

22-Jan-2022 02:35

Container	Damage type	Damage location
TGHU0398545	TORN	DOORSYSTEM
SUDU9200190	DENT	RIGHT
MSWU0112136	DENT	RIGHT
MMAU1197310	DENT	RIGHT
MNBU3580760	BENT	RIGHT
PONU7406152	BENT	LEFT
MRKU8210497	BENT	LEFT
PONU1640712	BENT	RIGHT
PONU1640712	DENT	RIGHT
PONU1640712	BENT	LEFT
PONU7610443	DENT	RIGHT
TLLU4891348	BENT	RIGHT
TLLU4891348	DENT	RIGHT
MSKU0428550	DENT	LEFT
SUDU8224182	DENT	RIGHT
TCNU6882299	BENT	RIGHT
TCNU6882299	DENT	RIGHT
TCNU6882299	BENT	LEFT
TCNU6882299	DENT	LEFT
MSKU8334951	BENT	RIGHT
MSKU8334951	BENT	LEFT
MRKU8594875	DENT	RIGHT
SUDU7545402	DENT	LEFT
FCBU8708813	HOLE	DOOR
SUDU6122113	DENT	RIGHT
MRKU9662362	DENT	RIGHT
MSKU9299114	DENT	RIGHT
MSKU9299114	BENT	RIGHT

Without any liability accepted
Constanta South Container Terminal
Planning Department

Container	Damage type	Damage location
MSKU9299114	DENT	LEFT
PONU7393409	BENT	RIGHT
TGBU5411503	DENT	RIGHT
TGHU8389555	BENT	LEFT
MRKU2120945	DENT	CORNERPOST
MMAU1077212	DENT	LEFT
TRHU4413320	DENT	RIGHT
TCLU7223262	BENT	RIGHT
FCIU8377496	HOLE	TOPROOF
SUDU8952803	DENT	RIGHT
MNBU0206607	DENT	RIGHT
MRKU4943156	BENT	LEFT
MRKU7023742	CUT	DOOR
MRKU0320899	DENT	RIGHT
MRKU0320899	BENT	LEFT
TCNU1955155	DENT	LEFT
TRHU5620600	DENT	LEFT
MRKU4819171	HOLE	BOTTOM
MRKU0136351	DENT	LEFT

Without any liability accepted
Constanta South Container Terminal
Planning Department