

DAMAGE REPORT

Inbound carrier: SUDEROOG

SUDR152E 152E

02-Jan-2022 03:58

Container	Damage type	Damage location
MVIU0031202	DENT	RIGHT
MRKU4548995	DENT	LEFT
CAAU6207400	DENT	RIGHT
CAAU6207400	DENT	DOORSYSTEM
MSKU2645200	TORN	CORNER
HASU4200847	DENT	LEFT
HASU4200847	BENT	LEFT
MRKU2309991	DENT	RIGHT
MRKU2697623	DENT	LEFT
UESU4579310	DENT	LEFT
MNBU0552528	HOLE	TOPROOF
MSKU1008085	DENT	RIGHT
MSKU1525067	BENT	LEFT
MSKU1525067	DENT	RIGHT
MSKU0707154	DENT	LEFT
TCNU2688705	IMO LABEL	FRONT
TCNU2688705	IMO LABEL	LEFT
TCNU2688705	IMO LABEL	RIGHT
TCNU2688705	IMO LABEL	BACK
MSKU0398780	DENT	RIGHT
MRKU1039844	IMO LABEL	RIGHT
MRKU2907817	DENT	RIGHT
MRKU2727477	BENT	LEFT

DISCHARGED AS LOADED

cle
MV "Suderoog"
Gibraltar

Without any liability accepted
Constanta South Container Terminal
Planning Department