

DAMAGE REPORT

Inbound carrier: SUDEROOG
SUDR202E 202E

15-Jan-2022 15:10

Container	Damage type	Damage location
MRKU3065708	DENT	CORNERPOST
MRKU2059819	DENT	LEFT
MRKU2059819	BENT	LEFT
TCKU7389430	DENT	CORNERPOST
MRKU4676424	BENT	LEFT
MRKU7939442	DENT	RIGHT
MSKU6284980	DENT	LEFT
UETU5698133	BENT	RIGHT
MRKU0574954	DENT	RIGHT
HASU4744157	DENT	RIGHT
HASU4744157	DENT	LEFT
MSKU9167822	IMO LABEL	LEFT
BLKU1269064	IMO LABEL	RIGHT
MSKU0163174	DENT	RIGHT
GESU6001478	BENT	RIGHT
GESU6001478	BENT	BOTTOM
GESU6001478	BENT	LEFT
GVCU4007952	DENT	RIGHT
MRKU6946745	CUT	BACK
PONU8092565	BENT	LEFT
TLLU8125340	DENT	LEFT
TCKU1137030	DENT	LEFT
PONU1891087	DENT	FRONT
TGHU2821770	DENT	DOORSYSTEM
FCBU8708578	DENT	LEFT
MRKU3305440	DENT	LEFT
SUDU7662918	DENT	RIGHT

clo
MV "Suderoog"
Gibraltar

DISCHARGED AS LOADED

Without any liability accepted
Constanta South Container Terminal
Planning Department