

DAMAGE REPORT

Inbound carrier: MAERSK NAKURU


MNKR345S

345S

13-Nov-2023 18:16

Container	Damage type	Damage location
MSKU1451391	DENT	LEFT
MRKU8045279	DENT	RIGHT
TCNU2741836	IMO LABEL	DOOR
TLHU2168347	BENT	RIGHT
TLHU2168347	BENT	LEFT
MNBU0487021	DENT	TOPROOF
MRSU6269349	DENT	LEFT
MSKU3223240	BENT	CORNERPOST
MSKU3223240	DENT	CORNER
TLHU2219613	BENT	LEFT
TLHU2219613	BENT	RIGHT
MRKU3551783	DENT	RIGHT
GCXU5811404	DENT	RIGHT
MAEU4084692	HOLE	TARPAULIN
MNBU0543043	DENT	RIGHT
TLLU5832170	BENT	LEFT
HASU4676031	BENT	RIGHT
MAEU4125071	HOLE	TARPAULIN
SUDU8594274	BENT	LEFT
SUDU8594274	BENT	RIGHT
TLHU2467918	BENT	LEFT
TCNU3526252	DENT	CORNERPOST
MRKU4729231	BENT	LEFT
MRKU4729231	IMO LABEL	RIGHT
MRSU4994900	BENT	FRONT
BEAU5098279	BENT	RIGHT
TCKU7398319	CUT	FLOOR
MRKU4713425	BENT	RIGHT


 MAERSK NAKURU
 FOR RECEIPT ONLY


 Without any liability accepted
 Container Terminal
 Planning Department
 Page 1 of 2

Container	Damage type	Damage location
MRKU6036787	DENT	RIGHT
TCKU6959380	BENT	RIGHT
TLHU2421692	BENT	RIGHT
MRSU3823360	DENT	CORNER
MRKU8560134	DENT	RIGHT
MAEU4056392	HOLE	TARPAULIN
HASU4600843	HOLE	RIGHT
HASU4600843	CUT	RIGHT
PONU8032000	RIPPED	DOOR
SEGU5157326	BENT	RIGHT
BMOU4479125	BENT	RIGHT
MRKU4457806	BENT	LEFT
MRKU5570838	CUT	DOOR
MRKU6989752	CRACK	CORNERPOST
MRSU4441340	DENT	LEFT
MRSU4441340	BENT	RIGHT
MSKU8589905	DENT	RIGHT
MSKU0329537	BENT	RIGHT
TLHU2545672	CUT	FLOOR
TLHU2545672	DENT	DOORSYSTEM
MSKU4121829	DENT	LEFT
MSKU4121829	IMO LABEL	RIGHT
PONU1669871	BENT	LEFT
TLHU0213690	BENT	RIGHT
MRKU5480159	DENT	LEFT
TCNU6501540	DENT	RIGHT
TCKU7091343	BENT	RIGHT
MRKU6762033	DENT	RIGHT
MAEU4193522	HOLE	TARPAULIN
MRSU4143011	DENT	LEFT
TRHU5172038	BENT	DOORSYSTEM

MAERSK NAKURU
FOR RECEIPT ONLY

Without any liability accepted
Constantia Ship Container Terminal
Stevedoring Department