

DAMAGE REPORT

Inbound carrier: NINA A
NIAA 095 06-Feb-2026 16:32

Container	Damage type	Damage location
TEMU8349186	DENT	FRONT
TEMU8349186	BENT	RIGHT
TEMU8349186	BENT	LEFT
MIEU3051704	BENT	FRONT
BEAU5185650	DENT	RIGHT
BEAU5185650	DENT	LEFT
MRSU3938461	DENT	RIGHT
TLLU6849373	BENT	LEFT
SUDU5483786	DENT	FRONT
SUDU5483786	DENT	RIGHT
SUDU5483786	DENT	LEFT
SUDU8606400	DENT	RIGHT
SUDU8606400	DENT	LEFT
TCNU3265945	BENT	RIGHT
TCNU3265945	BENT	LEFT
TLLU5257132	BENT	FRONT
TLLU5257132	BENT	RIGHT
TLLU5257132	DENT	RIGHT
TLLU5257132	BENT	LEFT
GESU6922430	DENT	RIGHT
MRKU2557299	DENT	RIGHT
MRKU2557299	DENT	LEFT
MRSU4871228	BENT	RIGHT
MRSU3343442	BENT	RIGHT
MRSU3343442	BENT	LEFT
HASU4011123	DENT	RIGHT
HASU4011123	BENT	FRONT
HASU4011123	BENT	RIGHT

M/V Nina A
Monrovia
IMO 9440605

Without any liability accepted
Constanta Page 1 of 6
Planning Department

Melito

Container	Damage type	Damage location
HASU4011123	DENT	LEFT
MRSU5214064	DENT	FRONT
MRSU5214064	DENT	RIGHT
MSKU1772200	BENT	FRONT
MSKU1772200	DENT	RIGHT
MSKU1772200	DENT	LEFT
MSKU9893764	BENT	RIGHT
MSKU9893764	DENT	RIGHT
MSKU9893764	BENT	LEFT
TCNU4363777	DENT	RIGHT
TCNU4363777	DENT	LEFT
MSKU4646910	DENT	RIGHT
MSKU4646910	DENT	LEFT
MRSU5030998	BENT	LEFT
TCNU2733830	RUSTED	RIGHT
TCNU2733830	BENT	LEFT
TCNU2733830	RUSTED	LEFT
TCNU2733830	BENT	RIGHT
MRSU3222250	BENT	LEFT
MRKU2523719	BENT	RIGHT
MRKU2523719	DENT	RIGHT
MRKU2523719	BENT	LEFT
MRKU5425362	BENT	RIGHT
MRKU5425362	DENT	RIGHT
MRKU5425362	BENT	LEFT
MRKU5425362	DENT	LEFT
FFAU1922098	DENT	LEFT
MSKU4466646	BENT	LEFT
MSKU4466646	BENT	BOTTOM
MSKU4466646	BENT	RIGHT
FBIU0010028	DENT	FRONT
FBIU0010028	DENT	LEFT
FBIU0010028	BENT	RIGHT
HASU1515413	DENT	CORNERPOST

Page 2 of 6
Without liability accepted
Constanta South Container Terminal
Planning Department

Metabo

M/V Nina A
Monrovia
IMO 9440605

Container	Damage type	Damage location
HASU1515413	BENT	RIGHT
HASU1515413	BENT	BOTTOM
HASU1515413	BENT	LEFT
HASU1390656	BENT	LEFT
HASU1390656	DENT	LEFT
HASU1390656	BENT	BOTTOM
HASU1390656	BENT	RIGHT
MRSU6369501	BENT	RIGHT
MSKU9347151	DENT	FRONT
MSKU9347151	BENT	RIGHT
MSKU9347151	BENT	LEFT
MSKU1538892	BENT	RIGHT
MSKU1538892	BENT	LEFT
MAEU9237942	DENT	RIGHT
MAEU9237942	DENT	LEFT
MSKU4714207	BENT	RIGHT
MSKU4714207	RUSTED	BACK
MSKU4714207	DENT	LEFT
MRKU3002593	DENT	RIGHT
MRKU3002593	BENT	LEFT
TCKU7491756	DENT	RIGHT
MRKU6339546	DENT	FRONT
MRKU6339546	RUSTED	FRONT
MRKU6339546	DENT	RIGHT
MRKU6339546	DENT	LEFT
MRKU6339546	BENT	LEFT
MRKU4444265	BENT	RIGHT
MRKU4444265	DENT	RIGHT
MRKU4444265	BENT	LEFT
SUDU6685837	DENT	FRONT
SUDU6685837	BENT	RIGHT
SUDU6685837	BENT	LEFT
TCNU5201071	DENT	RIGHT
TCNU5201071	BENT	RIGHT

RIGHT
Without any liability accepted
Costanta South Container Terminal
Planning Department
Page 3 of 16

1/V Nina A
Monrovia
NO 9440605

Meleto

Container	Damage type	Damage location
TCNU5201071	BENT	LEFT
MRKU3599046	BENT	RIGHT
MRKU3599046	DENT	LEFT
MRKU3599046	BENT	LEFT
TCNU8810805	BENT	RIGHT
TCNU8810805	DENT	RIGHT
TCNU8810805	BENT	LEFT
TCNU8810805	DENT	LEFT
MRSU4518210	DENT	FRONT
TEMU6680596	DENT	LEFT
TEMU6680596	DENT	RIGHT
TEMU6680596	BENT	LEFT
CAAU8969323	DENT	LEFT
MRKU6217743	DENT	LEFT
BEAU5917005	DENT	FRONT
MRKU2325159	BENT	RIGHT
MRKU2325159	DENT	RIGHT
MRKU2325159	BENT	LEFT
FFAU4836861	DENT	RIGHT
FFAU4836861	DENT	CORNERPOST
MRKU3926956	BENT	RIGHT
MRKU3926956	DENT	RIGHT
GATU8528673	BENT	RIGHT
GATU8528673	DENT	RIGHT
GATU8528673	DENT	CORNERPOST
GATU8528673	BENT	LEFT
GATU8528673	DENT	LEFT
MSKU9529623	BENT	RIGHT
MSKU9529623	RUSTED	RIGHT
MSKU9529623	BENT	LEFT
MSKU9529623	DENT	LEFT
MSKU9529623	RUSTED	LEFT
MRKU2995063	BENT	RIGHT
MRKU2995063	DENT	RIGHT

M/V Nina A
Monrovia
IMO 9440605

Without any liability accepted
Constanta South Container Terminal
Planning Department

Metabo

Container	Damage type	Damage location
MRKU2995063	DENT	LEFT
CIPU5066522	DENT	FRONT
CIPU5066522	DENT	RIGHT
CIPU5066522	DENT	LEFT
HASU4697332	DENT	RIGHT
MSKU9739131	BENT	FRONT
MSKU9739131	DENT	FRONT
MSKU9739131	BENT	RIGHT
MSKU9739131	DENT	RIGHT
MSKU9739131	BENT	LEFT
SUDU8539282	BENT	RIGHT
SUDU8539282	DENT	RIGHT
SUDU8539282	BENT	LEFT
SUDU8539282	BENT	FRONT
MRKU4066334	BENT	RIGHT
MRKU4066334	BENT	LEFT
MRKU5648129	BENT	RIGHT
MRKU5648129	BENT	LEFT
MRKU5648129	DENT	CORNERPOST
MRKU6446230	DENT	FRONT
MRKU6446230	DENT	RIGHT
MRKU6446230	BENT	RIGHT
MRKU6446230	BENT	LEFT
MRKU6446230	DENT	LEFT
CAAU9279087	DENT	RIGHT
CAAU9279087	DENT	FRONT
CAAU9279087	BENT	LEFT
MRSU3146042	DENT	FRONT
MRSU3146042	DENT	RIGHT
MRSU3146042	BENT	RIGHT
MRSU3146042	DENT	LEFT
MRSU5577012	DENT	RIGHT
MRSU5577012	BENT	RIGHT
MRSU5577012	BENT	FRONT

M/V Nina A
Monrovia
IMO 9440605

Without any liability accepted
Page 5 of 6
Constanța South Container Terminal
Planning Department

Melch

Container	Damage type	Damage location
MRSU5577012	BENT	LEFT
DFSU6365421	BENT	RIGHT
DFSU6365421	BENT	FRONT
DFSU6365421	DENT	LEFT
MRKU4872643	BENT	RIGHT
MRKU4872643	DENT	LEFT
MRKU4872643	DENT	CORNER
TGHU9848598	DENT	CORNERPOST
TGHU9848598	DENT	FRONT
TGHU9848598	DENT	RIGHT
TGHU9848598	DENT	LEFT
TRHU8052988	BENT	FRONT
TRHU8052988	BENT	LEFT
MRSU3525787	DENT	RIGHT
MRSU3525787	DENT	LEFT
MRSU3525787	DENT	FRONT
TCKU7078070	BENT	RIGHT
TCKU7078070	DENT	LEFT
MRKU4097485	DENT	RIGHT
MRKU4097485	DENT	LEFT
MRKU4128040	BENT	LEFT
HASU4092059	DENT	RIGHT
TCKU6961140	DENT	RIGHT
TCKU6961140	DENT	LEFT
GESU6148685	BENT	RIGHT
GESU6148685	DENT	RIGHT
MRKU4582475	DENT	RIGHT
MRKU4582475	DENT	LEFT

M/V Nina A
Monrovia
IMO 9440605

